

Ford



General information

Make	FORD
Model	FIESTA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual
0 - 60 mph	13.7 seconds

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G







Internet history

Entry 1		
Date		

2021-06-12

8

Listing price

Pictures

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-14
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	12
Total items failed	10

MOT #17	2024-03-07 14:04
MOT test number	219487753394
Result	✓ Passed
Next expiry date	2025-03-14
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #16	2024-02-28 10:58
MOT test number	376124566574
Result	🗙 Failed
FailOffside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ing(ii))	gress of dirt (5.3.4 (b)
Fail Offside Front Steering rack gaiter missing or no longer prevents the ingress of d	irt (2.1.3 (g) (ii))
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of	dirt (2.1.3 (g) (ii))
Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #15	2023-03-15 10:53
MOT test number	516607735851
Result	✓ Passed





MOT #14	2023-03-13 16:38
MOT test number	891919740415
Result	🗙 Failed
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	

MOT #13	2022-02-07 13:32
MOT test number	639324794050
Result	✓ Passed
Advice Tyre worn close to legal limit/worn on edge all (5.2.3 (e))	

MOT #12	2022-02-07 09:13
MOT test number	341824093020
Result	🗙 Failed
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail Offside Drive shaft joint constant velocity boot split or insecure, no longer prever (6.1.7 (g) (ii))	nts the ingress of dirt
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Tyre worn close to legal limit/worn on edge all (5.2.3 (e))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	

MOT #11	2021-02-12 16:15
MOT test number	499545467867
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #10	2020-02-04 13:50
MOT test number	627490950918
Result	✓ Passed
Advice Offside Front Lowe	er Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice Nearside Front Ant	i-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice Nearside Rear Tyre	e worn close to legal limit/worn on edge On legal limit of 1.6mm (5.2.3 (e))
Minor Offside Front Steeri (2.1.3 (g) (i))	ng rack gaiter damaged or deteriorated, but preventing the ingress of dirt
МОТ #9	2019-02-05 16:52
MOT test number	569027532555
Result	✓ Passed
MOT #8	2017-12-15 11:29
MOT test number	981414611207
Result	✓ Passed
MOT #7	2016-12-16 14:10
MOT test number	468200149709
Result	✓ Passed
MOT #6	2016-12-16 09:16
MOT test number	523480800776
Result	× Failed
Fail Nearside Front susper	nsion has excessive play in a lower suspension ball joint (2.5.B.1a)
MOT #5	2015-12-18 10:05

Result

MOT test number

🗸 Passed





MOT #4	2015-05-18 10:02
MOT test number	799878935162
Result	Passed
Notice Child seat fitted not allowing full inspection of adult belt	
MOT #3	2014-04-12 11:57
MOT test number	536732004198
Result	✓ Passed
Advice Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2	2013-04-16 17:34
MOT test number	467016503107
Result	✓ Passed
MOT #1	2013-02-22 11:36
MOT test number	145583653048
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 July 2024	Expires: 14 March 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Carrent registration Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-30
Last registration	2024-03-07
Complete history	See info



Registration #1	2010-03-30	11 mi
Registration #2	2013-02-22	13.025 mi
Registration #3	2013-04-16	13.481 mi
Registration #4	2014-04-12	23.731 mi
Registration #5	2015-05-18	36.713 mi
Registration #6	2015-12-18	43.163 mi
Registration #7	2016-12-16	46.137 mi
Registration #8	2016-12-16	46.137 mi
Registration #9	2017-12-15	51.652 mi
Registration #10	2019-02-05	59.771 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		01.777 mi





Car features

S0225	Air conditionin
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg
Additional information	
Fuel delivery	Multi-Point Injection

i dei delivery	Hale Fonte injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

AL63837