





General information

| Make | FIAT |
|---------------------|-------------------------|
| Model | TIPO MULTIJET EASY PLUS |
| Colour | White |
| Year of manufacture | 2017 |
| Top speed | 124 mph |
| 0 - 60 mph | 9.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 118 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 64.2 mpg |
| Consumption extra urban | 85.6 mpg |
| Consumption combined | 76.4 mpg |
| CO2 emission | 98 g/km |
| CO2 label | А |







Internet history

Entry 1

Date

2022-06-04

Pictures

Listing price

View report

4









source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-08-03 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 5 |

| MOT #6 | 2023-08-04 09:35 |
|---|------------------|
| MOT test number | 513958822296 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-03 |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) | |
| Advice Brake disc worn, pitted or scored, but not seriously weakened Front & Rear (1.1.14 (a) (ii)) | |

| MOT #5 | 20 | 23-08-04 09:35 |
|---|---|----------------|
| MOT test number | | 178732911104 |
| Result | | 🗙 Failed |
| | ock absorbers has light misting of oil (5.3.2 (b)) yre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Pass with rectificationRear Registration plate lamp does not illuminate simultaneously with theposition lamps (4.7.2 (a)) | | ith the |
| Advice Brake disc worn | , pitted or scored, but not seriously weakened Front & Rear (1.1.14 (| a) (ii)) |

| МОТ #4 | 2022-07-05 09:12 |
|-----------------|------------------|
| MOT test number | 406717890110 |
| Result | ✓ Passed |





| MOT #3 | 2021-06-22 15:25 |
|---|------------------|
| MOT test number | 824984102521 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2021-06-22 11:39 |
| MOT test number | 468573760305 |
| Result | 🗙 Failed |
| Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) | |
| Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| | |
| NOT #1 | 2020 05 20 10 40 |

| MOT #1 | 2020-05-20 10:46 |
|-----------------|------------------|
| MOT test number | 179407055666 |
| Result | ✓ Passed |



Tax & MOT check

| √ Taxed | ✓ MOT |
|-------------------------------------|---------------------------|
| Tax due: 1 September 2024 | Expires: 3 August 2024 |
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 3 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4 ARAPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and a second s | |
|---|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 8 |
| First mileage registration | 2017-06-12 |
| Last registration | 2023-08-04 |
| Complete history | <u>See info</u> |



| Registration #1 | 2017-06-12 | 28 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-05-20 | 48.691 mi |
| Registration #3 | 2021-06-22 | 68.103 mi |
| Registration #4 | 2021-06-22 | 68.103 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 10.300 est |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| S0482 | |
| \$0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 82% |
| Children | 60% |
| Pedestrian | 62% |
| Safety systems | 57% |
| Overall rating | 68% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1792 mm |
| Height | 1495 mm |
| Length | 4368 mm |
| Wheel base | 2638 mm |
| Kerb weight | 1370 kg |
| Max. allowed weight | 1795 kg |
| Additional information | |
| Fuel tank capacity | 50 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 7973051 |