



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 SPORT
Colour	Black
Year of manufacture	-
Top speed	120 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg







Internet history

Entry 1

Date	2021-07-14
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #18</b>	2022-07-19 11:29
<b>MOT test number</b>	184459449217
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-07-18
<b>Advice</b>	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Advice</b>	Rear Position lamp slightly affected by the operation of another lamp interaction with indicators (4.2.3 (c))

<b>MOT #17</b>	2022-07-19 08:20
<b>MOT test number</b>	959811805471
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Position lamp slightly affected by the operation of another lamp interaction with indicators (4.2.3 (c))
<b>Advice</b>	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a) (ii))
<b>Fail</b>	Offside Front Headlamp aim too high (4.1.2 (a))

<b>MOT #16</b>	2021-08-31 07:53
<b>MOT test number</b>	799414975744
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front bulk head corroded
<b>Advice</b>	Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
<b>Advice</b>	Lower Gearbox mounting defective
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened all brake discs corroded due to standing (1.1.14 (a) (ii))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2021-08-26 07:17

**MOT test number**

975618052401

**Result****✗ Failed****Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened all brake discs corroded due to standing (1.1.14 (a) (ii))**Fail** Brake performance not tested (1.2.1 (g))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Emissions not tested (8.2.1.2 (d))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Lower Gearbox mounting defective**MOT #14**

2020-07-09 09:46

**MOT test number**

367753533295

**Result****✓ Passed****MOT #13**

2020-07-09 09:46

**MOT test number**

900824615511

**Result****✗ Failed****Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Pass with rectification** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #12** 2019-05-15 13:36**MOT test number** 365391173778**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Play in steering rack inner joint(s)**MOT #11** 2018-05-09 14:06**MOT test number** 878605579933**Result** ✓ Passed**Advice** Offside brake cable slightly corroded**MOT #10** 2017-05-30 13:34**MOT test number** 722332092921**Result** ✓ Passed**MOT #9** 2016-05-10 15:15**MOT test number** 319565641181**Result** ✓ Passed**Advice** Slight play in both steering rack inner ends**MOT #8** 2015-05-29 14:32**MOT test number** 818489045115**Result** ✓ Passed**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #7** 2014-05-28 17:46**MOT test number** 389688844136**Result** ✓ Passed**Advice** Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-05-28 14:58**MOT test number** 167158044105**Result** ✗ Failed**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Lower Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-05-28 14:38**MOT test number** 836628343184**Result** ✓ Passed**MOT #4** 2012-05-21 14:57**MOT test number** 517932142165**Result** ✓ Passed**MOT #3** 2011-06-01 11:16**MOT test number** 265312151488**Result** ✓ Passed



MOT #2	2010-01-05 10:41
MOT test number	673485300020
Result	✓ Passed
Notice	FRONT DISC'S WELL WORN
Notice	FRONT PADS GETTING LOW
Notice	REAR BOX CORRODED
Notice	REAR PADS LOW AND ON LIMIT

MOT #1	2008-12-30 13:12
MOT test number	254265868358
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>WN55PJU</b>
Plate since	2019-03-28
Current registration	<b>WN55PJU</b>
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-12-30
Last registration	2022-07-19
Complete history	<a href="#">See info</a>



Registration #1	2005-12-30	26 mi
Registration #2	2008-12-30	27.741 mi
Registration #3	2010-01-05	35.701 mi
Registration #4	2011-06-01	42.565 mi
Registration #5	2012-05-21	49.458 mi
Registration #6	2013-05-28	54.735 mi
Registration #7	2014-05-28	59.934 mi
Registration #8	2014-05-28	59.940 mi
Registration #9	2015-05-29	64.683 mi
Registration #10	2016-05-10	68.609 mi
Registration #11	2016-05-10	68.609 mi
Registration #12	2016-05-10	68.609 mi
Registration #13	2016-05-10	68.609 mi
Registration #14	2016-05-10	68.609 mi
Registration #15	2016-05-10	68.609 mi
Registration #16	2016-05-10	68.609 mi
Registration #17	2016-05-10	68.609 mi
Registration #18	2016-05-10	68.609 mi
Registration #19	2016-05-10	68.609 mi
Registration #20	2016-05-10	68.609 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1893 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1088 kg
Max. allowed weight	1553 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FX6N2832539