




report date: 2024-03-29

## General information

Make	VOLVO
Model	S80 SE LUX
Colour	Blue
Year of manufacture	2009
Top speed	143 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 4.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Gas / Diesel
Consumption city	18.6 mpg
Consumption extra urban	38.7 mpg
Consumption combined	27.7 mpg
CO2 emission	241 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-08-11
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-08-10
Pictures	67
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-13
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	20
Total items failed	5

MOT #17	2023-12-28 11:32
MOT test number	944567546242
Result	✓ Passed
Next expiry date	2025-01-13
Advice	Exhaust mounting defective middle exhaust hanger broken (6.1.2 (a))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #16	2023-12-28 11:32
MOT test number	693039031473
Result	✗ Failed
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Exhaust mounting defective middle exhaust hanger broken (6.1.2 (a))

MOT #15	2023-01-14 11:31
MOT test number	459888252128
Result	✓ Passed
Advice	Front Lower Suspension arm corroded but not seriously weakened both side (5.3.3 (b) (i))
Advice	Front Outer Track rod end slightly misaligned both side (2.1.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (iii))

**MOT #14** 2021-11-30 14:43**MOT test number** 688362215797**Result** ✓ Passed**MOT #13** 2021-02-25 10:02**MOT test number** 511109077858**Result** ✓ Passed**MOT #12** 2020-02-21 16:56**MOT test number** 740083419811**Result** ✓ Passed**MOT #11** 2020-02-21 15:30**MOT test number** 722912155996**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Nearside Rear Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))**MOT #10** 2019-02-25 17:37**MOT test number** 855585609678**Result** ✓ Passed**Advice** Central Exhaust mounting defective (6.1.2 (a))**MOT #9** 2019-02-21 15:46**MOT test number** 321076114168**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Central Exhaust mounting defective (6.1.2 (a))

**MOT #8** 2018-03-01 09:16**MOT test number** 580137865704**Result** ✓ Passed**Advice** Central Items removed from driver's view prior to test**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2017-02-20 10:50**MOT test number** 867254847142**Result** ✓ Passed**Advice** Offside Front tyre worn on inner**MOT #6** 2016-02-22 14:19**MOT test number** 747941101103**Result** ✓ Passed**Advice** Under trays fitted**MOT #5** 2015-02-23 12:14**MOT test number** 786694655046**Result** ✓ Passed**Notice** Both rear tyres slightly perished.**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-02-25 11:45**MOT test number** 775306354086**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2013-02-28 15:33
MOT test number	495359753028
Result	✓ Passed
<div><div>Advice</div>Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)</div> <div><div>Notice</div>Items removed from driver's view prior to test</div>	

MOT #2	2012-03-02 09:59
MOT test number	137862662438
Result	✓ Passed

MOT #1	2012-01-03 11:18
MOT test number	706343702086
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
13 January 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	13 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	L
<b>Single payment (12 months)</b>	£ 665,00,-
<b>Single six month payment</b>	£ 365,75,-
<b>Total payable by 12 monthly instalments</b>	£ 698,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>DE58XBG</b>
Plate since	2024-03-29
Current registration	<b>DE58XBG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-02-02
Last registration	2023-12-28
Complete history	<a href="#">See info</a>



Registration #1	2009-02-02	10 mi
Registration #2	2012-01-03	34.789 mi
Registration #3	2012-03-02	35.578 mi
Registration #4	2013-02-28	39.267 mi
Registration #5	2014-02-25	43.568 mi
Registration #6	2015-02-23	46.942 mi
Registration #7	2016-02-22	51.091 mi
Registration #8	2017-02-20	54.732 mi
Registration #9	2018-03-01	57.963 mi
Registration #10	2019-03-01	61.217 mi
Registration #11	2020-03-01	64.471 mi
Registration #12	2021-03-01	67.725 mi
Registration #13	2022-03-01	70.979 mi
Registration #14	2023-03-01	74.233 mi
Registration #15	2023-09-01	77.487 mi
Registration #16	2023-11-01	80.741 mi
Registration #17	2023-12-01	83.995 mi
Registration #18	2023-12-28	87.249 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1659 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	4356648
---------------	---------