



MJ080FT


report date: 2024-03-29

General information

Make	AUDI
Model	A5 TFSI SE
Colour	Grey
Year of manufacture	2008
Top speed	143 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	230 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-05
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-03-18
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	32
Total items failed	5

MOT #18	2023-03-15 11:01
MOT test number	608155069260
Result	✓ Passed
Next expiry date	2024-03-18
Advice	Oil leak, but not excessive oil around engine (8.4.1 (a) (i))

MOT #17	2022-03-19 10:46
MOT test number	354912110426
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2021-04-06 13:13
MOT test number	977649927457
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2020-05-01 09:34
MOT test number	816056347822
Result	✓ Passed

**MOT #14** 2020-04-23 12:46**MOT test number** 193161483316**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Nail in tyre**MOT #13** 2019-04-13 09:53**MOT test number** 152443102903**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2019-04-13 08:51**MOT test number** 485055634129**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))**MOT #11** 2018-04-27 10:58**MOT test number** 826287082977**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #10** 2018-04-27 10:58**MOT test number** 979113886608**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #9 2017-04-22 09:48

MOT test number 427798976614

Result ✓ Passed

MOT #8 2016-04-13 12:56

MOT test number 750603393839

Result ✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #7 2016-04-13 12:56

MOT test number 137951449403

Result ✗ Failed

Pass with rectification Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #6** 2015-04-18 12:55**MOT test number** 425078305114**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/s/r and n/s/r tyre scrubbing off on inne edge
- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Notice** Light cracks on both rear tyres
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #5 2014-04-23 14:17**MOT test number** 775573714165**Result** ✓ Passed

- Notice** Both rear tyres scrubbing of on inner edges
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Slight damage on number plates
- Notice** Under-trays fitted obscuring some underside components


**MOT #4** 2014-04-23 14:17**MOT test number** 679583714123**Result** ✗ Failed**Notice** Both rear tyres scrubbing of on inner edges**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Notice** Slight damage on number plates**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-04-24 14:04**MOT test number** 335724113175**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-04-27 17:06**MOT test number** 239418912151**Result** ✓ Passed**MOT #1** 2011-04-20 15:45**MOT test number** 928100511155**Result** ✓ Passed



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-29
Last registration	2023-03-15
Complete history	See info



Registration #1	2008-04-29	6 mi
Registration #2	2011-04-20	21.741 mi
Registration #3	2012-04-27	29.984 mi
Registration #4	2013-04-24	38.822 mi
Registration #5	2014-04-23	45.218 mi
Registration #6	2015-04-18	51.818 mi
Registration #7	2016-04-13	56.741 mi
Registration #8	2016-04-13	56.741 mi
Registration #9	2017-04-22	62.640 mi
Registration #10	2018-04-27	71.220 mi
Registration #11	2019-04-22	75.000 mi
Registration #12	2019-04-22	75.000 mi
Registration #13	2019-04-22	75.000 mi
Registration #14	2019-04-22	75.000 mi
Registration #15	2019-04-22	75.000 mi
Registration #16	2019-04-22	75.000 mi
Registration #17	2019-04-22	75.000 mi
Registration #18	2019-04-22	75.000 mi
Registration #19	2019-04-22	75.000 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1410 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CAB 019230