





### General information

Make	VOLKSWAGEN	
Model	PASSAT EXECUTIVE TDI BLUEMOTION TECHN	
Colour	Red	
Year of manufacture	2014	
Top speed	132 mph	
0 - 100 km/h	10.0 seconds	
0 - 60 mph	10.0 seconds	
Gearbox	6 speed Manual	

## Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	120 g/km
CO2 label	С





## MOT history

MOT expiry date	2024-08-14
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #9	2023-07-24 11:10
MOT test number	978755955231
Result	✓ Passed
Next expiry date	2024-08-14
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear brake discs corroded	

MOT #8	2022-08-10 08:36
MOT test number	394216223918
Result	✓ Passed
Advice Rear brake pads getting low and brake discs corroded	

MOT #7	2021-0	08-10 10:30
MOT test	number 609	782009122
Result		🗸 Passed
Advice	Offside Front Nail in tyre	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))	
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	



MOT #6	20	020-08-15 08:38
MOT test	number	741790284017
Result		🗸 Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #5		2019-07-18 11:52
MOT test	number	785242177607
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #4	2019-07-18 08:43	
MOT test number	427208605305	
Result	× Failed	
Advice Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Nearside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))		

MOT #3	2018-07-30 13:02
MOT test number	324110166462
Result	✓ Passed

RJ14OTD report date: 2024-03-29





MOT #2	2017-09-20 09:53
MOT test number	406224547048
Result	✓ Passed
MOT #1	2017-06-08 13:14
MOT #1 MOT test number	2017-06-08 13:14 612629053268



Tax & MOT check

<b>Tax due:</b> 1 April 2025	✓ Taxed	<b>Expires:</b> 14 August 2024	мот
Tax status			Valid until 1 April
Days left			336
MOT expiry date			14 August 2024
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	

Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

#### Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
**********	
*********	
**********	
*********	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-06-23
Last registration	2023-07-24
Complete history	See info



Registration #1	2014-06-23	8 mi
Registration #2	2017-06-08	22.792 mi
Registration #3	2017-09-20	23.271 mi
Registration #4	2018-07-30	40.905 mi
Registration #5	2019-07-18	52.191 mi
Registration #6		11.177 esi
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		10.200 mi

More info >





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1471 kg
Max. allowed weight	2180 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CFFBK74752