



WFIO PXD

report date: 2024-03-29

General information

Make	FIAT
Model	GRAND PUNTO MULTIJET GP
Colour	Grey
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	190 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg





Internet history

Entry 1

Date	2021-07-27
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #14</b>	2021-09-14 12:17
<b>MOT test number</b>	496559799821
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-13
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Rear exhaust deteriorated/corroded

<b>MOT #13</b>	2021-07-13 12:11
<b>MOT test number</b>	345949916671
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>MAJOR</b>	Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2020-07-07 08:25

**MOT test number**

621991509118

**Result**

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #11**

2019-07-16 08:03

**MOT test number**

591769802849

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #10**

2018-07-19 09:44

**MOT test number**

725450317053

**Result**

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9** 2018-07-19 08:33**MOT test number** 628888614793**Result** ✗ Failed**MAJOR** Brake fluid contaminated (1.8 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2017-07-19 09:09**MOT test number** 230403179539**Result** ✓ Passed**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**MOT #7** 2016-07-13 15:43**MOT test number** 685155798174**Result** ✓ Passed**MOT #6** 2016-07-13 08:45**MOT test number** 953401533140**Result** ✗ Failed**Advice** Front tyres wearing on inner edges**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Tyre worn close to the legal limit n/s and o/s (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #5

2015-07-23 13:37

MOT test number

516834705256

Result

✓ Passed

- Notice

Nearside rear tyre bald on edge
- Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Nearside front tyre worn on edge
- Notice

Offside rear tyre worn on edge
- Notice

Engine covers fitted obscuring some components in the engine bay
- Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

Offside front tyre worn on edge

**MOT #4** 2015-07-23 10:08**MOT test number** 788464005271**Result** ✗ Failed

- Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Offside front tyre worn on edge
- Notice** Nearside rear tyre bald on edge
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Front sub frame bracing bar distorted
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nearside front tyre worn on edge
- Notice** Offside rear tyre worn on edge
- Notice** Brake pedal anti-slip provision worn

**MOT #3** 2014-08-26 11:08**MOT test number** 926318534296**Result** ✓ Passed**MOT #2** 2014-04-26 10:04**MOT test number** 236566414469**Result** ✓ Passed



MOT #1	2013-06-01 10:45
MOT test number	588502953173
Result	✓ Passed





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-31
Last registration	2021-09-14
Complete history	<a href="#">See info</a>



Registration #1	2010-03-31	15 mi
Registration #2	2013-06-01	26.410 mi
Registration #3	2014-04-26	34.179 mi
Registration #4	2014-08-26	36.635 mi
Registration #5	2015-07-23	46.340 mi
Registration #6	2015-07-23	46.340 mi
Registration #7	2016-07-13	53.251 mi
Registration #8	2016-07-13	53.251 mi
Registration #9	2016-07-13	53.251 mi
Registration #10	2016-07-13	53.251 mi
Registration #11	2016-07-13	53.251 mi
Registration #12	2016-07-13	53.251 mi
Registration #13	2016-07-13	53.251 mi
Registration #14	2016-07-13	53.251 mi
Registration #15	2016-07-13	53.251 mi
Registration #16	2016-07-13	53.251 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1105 kg
Max. allowed weight	1665 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	3307850