



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 111 CDI COMPACT P/V
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-15
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-12-05
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #14	2021-12-06 15:45
MOT test number	600385449924
Result	✓ Passed
Next expiry date	2022-12-05

MOT #13	2021-02-25 15:58
MOT test number	779290508065
Result	✓ Passed
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #12	2021-02-25 15:58
MOT test number	354767760827
Result	✗ Failed
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #11** 2019-11-13 15:15**MOT test number** 267560058708**Result** ✓ Passed**MOT #10** 2018-11-16 11:23**MOT test number** 701614272181**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #9** 2018-11-12 08:54**MOT test number** 724277677584**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Spare wheel carrier insecure (6.1.5 (a))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**MOT #8** 2017-11-11 07:39**MOT test number** 764472786623**Result** ✓ Passed**Advice** F pads wearing**Advice** F brake balance 29% just passed**Advice** Both rear indicators going white**Advice** Slight bind on o/s/f wheel

**MOT #7** 2016-11-12 08:41**MOT test number** 133486343696**Result** ✓ Passed

- Advice** Rear pads wearing
- Advice** Propshaft noisy
- Advice** Engine oil leak
- Advice** All 4 tyres wearing
- Advice** O/s door mirror condition

MOT #6 2015-11-07 08:18**MOT test number** 407390868902**Result** ✓ Passed

- Advice** F roll bar bushes wearing
- Advice** F/r pads wearing
- Advice** Slight distortion in f discs
- Advice** O/s door mirror condition
- Advice** Parking brake requires attention

MOT #5 2014-08-30 12:18**MOT test number** 425062944257**Result** ✓ Passed

- Notice** Advise near side rear tyre, tread wearing low 2.0mm
- Notice** Advise off side front tyre, slight damage to outer side wall



MOT #4	2013-08-23 11:56
MOT test number	845925333291
Result	✓ Passed
<div>Advice</div> Parking brake lever has little reserve travel (3.1.6b)	
MOT #3	2012-08-16 12:04
MOT test number	846169622260
Result	✓ Passed
MOT #2	2012-08-16 12:04
MOT test number	387329522438
Result	✗ Failed
<div>Pass with rectification</div> Offside Stop lamp not working (1.2.1b)	
MOT #1	2011-09-05 12:06
MOT test number	969568641271
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
5 April 2024

✕
MOT

Expired:
5 December 2022

Tax status	Expired at 5 April 2024
Days left	25 days too late
MOT expiry date	5 December 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	KT08WCF
Plate since	2024-03-29
Current registration	KT08WCF
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-06-20
Last registration	2021-12-06
Complete history	See info



Registration #1	2008-06-20	22 mi
Registration #2	2011-09-05	60.945 mi
Registration #3	2012-08-16	65.003 mi
Registration #4	2013-08-23	70.113 mi
Registration #5	2014-08-30	78.463 mi
Registration #6	2015-11-07	88.556 mi
Registration #7	2016-11-12	97.074 mi
Registration #8	2017-11-11	104.516 mi
Registration #9	2018-05-20	111.277 mi
Registration #10	2019-05-20	118.277 mi
Registration #11	2020-05-20	125.277 mi
Registration #12	2021-05-20	132.277 mi
Registration #13	2022-05-20	139.277 mi
Registration #14	2023-05-20	146.277 mi
Registration #15	2024-05-20	153.277 mi

More info >



Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Dimensions & weight

Width	1906 mm
Height	1902 mm
Length	4748 mm
Kerb weight	1885 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	64698051605488