



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC EXPRESSION DCI
Colour	Blue
Year of manufacture	2009
Top speed	116 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	106 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	130 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-12-07
Pictures	45
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	31
Total items failed	6

MOT #16 2023-09-08 08:07

MOT test number 264941999636

Result ✓ Passed

Next expiry date 2024-09-07

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush bonding failing (5.3.4 (a) (i))

Advice Coolant leak coolant level low

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush bonding failing (5.3.4 (a) (i))

MOT #15 2022-09-01 11:39

MOT test number 536160905366

Result ✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material Both sides at flexi join (1.1.11 (c))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bushes both sides NSF and OSF (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing And side wall perished (5.2.3 (d) (ii))

**MOT #14** 2021-08-18 08:06**MOT test number** 258802399242**Result** ✓ Passed**Advice** Wind screen scratched**Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2020-08-27 10:31**MOT test number** 984427043425**Result** ✓ Passed**Advice** Offside Rear Lower spring rusty**MOT #12** 2020-08-27 10:31**MOT test number** 847515192558**Result** ✗ Failed**Pass with rectification** Nearside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Lower spring rusty**Pass with rectification** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**MOT #11** 2019-08-13 07:54**MOT test number** 792678849327**Result** ✓ Passed**Advice** Offside Rear Lower spring rusty**Advice** Wind screen scratched

**MOT #10** 2018-08-14 14:48**MOT test number** 634870243856**Result** ✓ Passed

- Advice** Nearside Rear Outer Tyre wall badly scrubbed
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Advice** Off side rear and off side front tyres perishing on outer walls

MOT #9 2018-08-14 09:35**MOT test number** 162488201608**Result** ✗ Failed

- Advice** Off side rear and off side front tyres perishing on outer walls
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Outer Tyre has ply or cords damaged (5.2.3 (d) (ii))
- Advice** Nearside Rear Outer Tyre wall badly scrubbed

MOT #8 2017-08-24 09:21**MOT test number** 371784190668**Result** ✓ Passed

- Advice** Rear tyre valves perished
- Advice** Off side rear light unit wiring connector and bulb holder burning out in pins
- Advice** Near side front and near side rear outer tyre side walls scrubbed

MOT #7 2016-08-09 10:43**MOT test number** 546761838558**Result** ✓ Passed

- Advice** Unable to confirm rear inner brake pads

**MOT #6** 2015-08-14 09:07**MOT test number** 215456125261**Result** ✓ Passed**MOT #5** 2015-08-14 09:07**MOT test number** 909636625277**Result** ✗ Failed

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4 2014-08-29 10:25**MOT test number** 775221744289**Result** ✓ Passed

Notice Near side rear tyre wearing on outer edge

MOT #3 2014-08-22 10:18**MOT test number** 745124334227**Result** ✗ Failed

Fail Rear Rear fog lamp not working (1.3.2b)

Notice Near side rear tyre wearing on outer edge

Fail Rear Rear fog lamp tell tale not working (1.3.1b)

MOT #2 2013-08-07 12:23**MOT test number** 466459813255**Result** ✓ Passed

Notice Near side rear tyre wearing on outer edge



MOT #1	2012-08-20 09:15
MOT test number	466123232265
Result	✓ Passed
<div>Notice Front tyres wearing on both edges</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	2024-03-29
Agreement type	RENT TO BUY
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-01
Last registration	2023-09-08
Complete history	See info



Registration #1	2009-09-01	24 mi
Registration #2	2012-08-20	22.327 mi
Registration #3	2013-08-07	27.432 mi
Registration #4	2014-08-22	32.721 mi
Registration #5	2014-08-29	32.916 mi
Registration #6	2015-08-14	37.193 mi
Registration #7	2016-08-09	41.766 mi
Registration #8	2017-08-24	47.383 mi
Registration #9	2018-08-14	51.465 mi
Registration #10	2019-08-29	55.547 mi
Registration #11	2020-08-29	59.629 mi
Registration #12	2021-08-29	63.711 mi
Registration #13	2022-08-29	67.793 mi
Registration #14	2023-08-29	71.875 mi
Registration #15	2023-08-29	71.875 mi
Registration #16	2023-08-29	71.875 mi
Registration #17	2023-08-29	71.875 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1385 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	D044925
---------------	---------