





General information

Make	BMW
Model	120 118D M SPORT
Colour	Blue
Year of manufacture	2006
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP	0 < 101 A
Max. torque	280 Nm at 2.000 rpm	101 - 120 ^B _C
Engine capacity	1.995 cc	121 - 140 E
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185
Consumption city	36.7 mpg	186 - 225 J
Consumption extra urban	62.8 mpg	225+ L
Consumption combined	50.4 mpg	
CO2 emission	150 g/km	
CO2 label	F	





Internet history

E	Intrv	1

Date Pictures 2021-06-09

19

Listing price

View report









source: yesauto.com



MOT history

MOT expiry date	2024-08-09
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	36
Total items failed	5

MOT #22	2023-08-10 15:11
MOT test number	284701120753
Result	✓ Passed
Next expiry date 2024-08-0	
Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #21	2023-08-10 08:53
MOT test	number 912058032585
Result	× Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #20		2022-06-15 14:37
MOT test	number	541977299537
Result		✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	



OV06RHE
report date: 2024-03-29

MOT #19		2022-06-15 13:23
MOT test	number	625139808462
Result		🗙 Failed
Advice	O/s/r tyre had less than 10psi @ start of test	
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	

MOT #18		2021-05-24 12:39
MOT test	number	832984293080
Result		✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice (5.3.4 (a)	Offside Rear Lower Suspension arm pin or bush worn but not resulting in ex (i))	ccessive movement

MOT #17	2020-06-03 10:47
MOT test number	287568978264
Result	Passed
Advice Covers on underside	
Advice Front osf/nsf flexi brake pipe hose perishing	
Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in	excessive movement
(5.3.4 (a) (i))	





MOT #16		2020-06-02 15:52
MOT test	number	814074514240
Result		🗙 Failed
Advice (5.3.4 (a)	Offside Rear Lower Suspension arm pin or bush worn but not resulting in (i))	excessive movement
Advice	Front osf/nsf flexi brake pipe hose perishing	
MAJOR centre of t	Offside Rear Tyre has a cut in excess of the requirements deep enough to read (5.2.3 (d) (i))	o reach the ply or cords
Advice	Covers on underside	
MOT #15		2019-06-04 11:51
MOT test	number	469394885132
Result		✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	

Auvice	Nearside Front brake hose signify deteriorated (1.1.12 (b) (ii))

MOT #14		2018-05-03 15:43
MOT test number		740761019351
Result		✓ Passed
Advice (4.1.E.1)	Nearside Rear Tyre worn close to the legal limit 2.0 mm, bald on inner edg	e close to cords
Advice	Front Brake hose slightly deteriorated both (3.6.B.4d)	
Advice	Offside Rear wheel bearing has slight play (2.6.2)	

MOT #13	2017-05-09 10:01
MOT test number	366504683816
Result	✓ Passed
Advice Nearside Rear n/s/r tyre wearing on both shoulders	





MOT #12	2016-05-12 11:35
MOT test number	264982090048
Result	✓ Passed
MOT #11	2016-05-12 07:56
MOT test number	444771495449
Result	🗙 Failed
Fail Nearside Rear brake caliper has restricted free movement (3.5.1k)	
FailNearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
MOT #10	2015-06-04 10:22

MO1 #10	2015-00-04 10:22
MOT test number	396455955186
Result	✓ Passed

MOT #9	2014-06-12 11:45
MOT test number	289053464102
Result	✓ Passed

MOT #8		2013-06-24 10:22
MOT test number		997305273179
Result		✓ Passed
Advice (8.3.1d)	Nearside Front Windscreen has damage to an area less than a 40mm cir	cle outside zone 'A'

MOT #7	2013-02-26 12:57
MOT test number	817687053010
Result	✓ Passed



МОТ #6		2013-02-25 13:36
MOT test number		186936453454
Result		🗙 Failed
Fail Front Brake	pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Rear Brake	pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #5		2012-02-27 12:56
MOT test number		166748752475
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

MOT #4		2011-03-18 11:08
MOT test number		465497771017
Result		✓ Passed
Notice	Off side front tyre worn on edge (not urgent)	
Notice	Near side front tyre worn low border line	

MOT #3		2010-03-23 14:32
MOT test	number	521952680053
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

Notice

Front brake pads worn low







🗸 Passed

MOT #2	2010-03-18 13:25
MOT test number	993017270095
Result	🗙 Failed
Notice Child seat fitted not allowing full inspection of adult belt	
Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #1	2009-01-21 11:20
MOT test number	390961729088

Result



OVO6RHE report date: 2024-03-29

Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 May 2025	Expires: 9 August 2024
Tax status	Valid until 1 May
Days left	366
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lampe
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this BMW had different number plates	5.
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



OVO6RHE report date: 2024-03-29

Mileage check

In miles
24
2006-05-01
2023-08-10
<u>See info</u>



Registration #1	2006-05-01	13 mi
Registration #2	2009-01-21	31.126 mi
Registration #3	2010-03-18	58.823 mi
Registration #4	2010-03-23	58.884 mi
Registration #5	2011-03-18	41.361 mi
Registration #6	2012-02-27	45.609 mi
Registration #7	2013-02-25	52.259 mi
Registration #8	2013-02-26	52.283 mi
Registration #9	2013-06-24	52.806 mi
Registration #10	2014-06-12	61.985 mi
Registration #11	2015-06-04	70.277 mi
Registration #12	2016-05-12	79.038 mi
Registration #13		11.222 esi
Registration #14		11.227 est
Registration #15		
-		
Registration #16		10.202 est
Registration #16 Registration #17		10.202 est 10.202 est
-		10.202 est 10.202 est 10.202 est
Registration #17		10.202 est 10.202 est 10.202 est 10.202 est
Registration #17 Registration #18		10.202 est 10.202 est 10.202 est 10.202 est 10.202 est
Registration #17 Registration #18 Registration #19		10.202 46 01.202 46 01.202 46 01.202 46 01.202 46 01.202 46
Registration #17 Registration #18 Registration #19 Registration #20		10.000 est 10.000
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		10.000 est 10.000
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		10.000 460 10.000 460 10.000 460 10.000 460 10.000 460 10.000 460 10.000 460 10.000 460 10.000 460







Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1751 mm
Height	1430 mm
Length	4227 mm
Wheel base	2660 mm
Kerb weight	1310 kg
Max. allowed weight	1810 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles	2
Engine number	84716312