





report date: 2024-03-28

General information

Make	PEUGEOT
Model	PARTNER HDI TEPEE OUTDOOR
Colour	Grey
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/13



MT14NUW report date: 2024-03-28

MOT history

MOT expiry date	2024-06-27
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	34
Total items failed	6

MOT #10	2023-06-21 09:37
MOT test number	205148149228
Result	✓ Passed
Next expiry date	2024-06-27
Advice Brake pad(s) wearing thin Both Rear (1.1.13 (a) (ii))	

MOT #9		2023-06-21 09:37
MOT test number		205053217607
Result		X Failed
Pass with rectification	Position lamp not working Nearside Front (4.2.1 (a) (ii))	
Pass with rectification	Passenger's seat insecure Nearside Rear (6.2.6 (a) (ii))	
Advice Brake pad(s) we	aring thin Both Rear (1.1.13 (a) (ii))	

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT #8 2022-06-24 12:10

MOT test number 986367561133

Result ✓ Passed

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge NSR tyre worn outer edge (5.2.3 (e))

Advice Nearside Front Inner Play in steering rack inner joint(s)

Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords NSR tyre deep cut to outer sidewall (5.2.3 (d) (i))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view Stone chip Zone A (3.2 (a) (i))

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords OSR tyre deep cut to tread (5.2.3 (d) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge OSF tyre worn inner edge (5.2.3 (e))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords NSF tyre deep cut to outer sidewall (5.2.3 (d) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #7 2022-06-24 09:29

MOT test number 752010536715

Result

× Failed

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords NSF tyre deep cut to outer sidewall (5.2.3 (d) (i))

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords OSR tyre deep cut to tread (5.2.3 (d) (i))

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge OSF tyre worn inner edge (5.2.3 (e))

Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords NSR tyre deep cut to outer sidewall (5.2.3 (d) (i))

Advice Nearside Front Inner Play in steering rack inner joint(s)

Advice Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view Stone chip Zone A (3.2 (a) (i))

Advice Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair Front service brake effort low (1.2.1 (c))

Fail Nearside Rear Passenger's seat insecure (6.2.6 (a) (ii))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge NSR tyre worn outer edge (5.2.3 (e))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #6 2021-06-28 12:14

MOT test number 651961928768

Result
✓ Passed

Minor Offside Front Windscreen damaged but not adversely affecting driver's view Stone chip Zone A (3.2 (a) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Central Rear Lower Spare wheel carrier slightly loose

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair Front service brake effort low (1.2.1 (c))

MOT #5 2021-06-25 10:20

MOT test number 876613698426

Result X Failed

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Central Rear Lower Spare wheel carrier slightly loose

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Fuel tank leaking Leaking from upper surface, suspect fuel pump/level sensor seal (6.1.3 (b) (i))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view Stone chip Zone A (3.2 (a) (i))

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Front Service brake requirements only just met. It would appear that the braking system requires adjustment or repair Front service brake effort low (1.2.1 (c))

Fail Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4	2020-06-22 08:39
MOT test number	517711759995
Result	✓ Passed
MOT #3	2019-05-28 10:30
MOT test number	200282023450
Result	✓ Passed
MOT #2	2018-05-29 11:23
MOT test number	474960436849
Result	✓ Passed
MOT #1	2017-05-02 11:53
MOT test number	489878841559
Result	✓ Passed

CarCheck.co.uk page 6/13





report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

MT14NUW

report date: 2024-03-28

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

More info >



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-05-30
Last registration	2023-06-21
Complete history	See info



Registration #1	2014-05-30	19 mi
Registration #2	2017-05-02	23.178 mi
Registration #3	2018-05-29	28.325 mi
Registration #4	2019-05-28	32.813 mi
Registration #5	2020-06-22	37.402 mi
Registration #6	2021-06-25	42.364 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.074
Registration #11		10.777 es

More info >

CarCheck.co.uk page 12/13



MT14NUW report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

				~			
ונו	men:	CIOT	nc -	λ.	WAI	α	ht.
וט	пеп	SIUI	13	CX.	$VV \subset I$	ш	TTU.

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1624 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEV0015444

CarCheck.co.uk page 13/13