



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 ACTIVE AWD
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.4 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-05-22
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-26
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #13	2023-06-27 10:15
MOT test number	523589155375
Result	✓ Passed
Next expiry date	2024-06-26
Advice	Front tyres wearing outer edges

MOT #12	2022-06-06 11:49
MOT test number	665555188391
Result	✓ Passed

MOT #11	2021-02-26 13:40
MOT test number	767186172649
Result	✓ Passed

MOT #10	2019-10-31 13:32
MOT test number	627650223216
Result	✓ Passed

**MOT #9** 2019-04-15 14:47**MOT test number** 217657717234**Result** ✓ Passed

- Advice** Front Play in steering rack inner joint(s) both
- Advice** Oil leak, but not excessive engine bay area (8.4.1 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing inner edge also worn (5.2.3 (d) (ii))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #8 2019-04-15 08:07**MOT test number** 540893964963**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- Fail** Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))
- Advice** Front Play in steering rack inner joint(s) both
- Advice** Offside Front Tyre slightly damaged/cracking or perishing inner edge also worn (5.2.3 (d) (ii))
- Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Oil leak, but not excessive engine bay area (8.4.1 (a) (i))

MOT #7 2018-04-28 08:12**MOT test number** 679919132148**Result** ✓ Passed

- Advice** Oil leak
- Advice** Undertrays and engine covers fitted
- Advice** General corrosion on underside of vehicle

**MOT #6** 2017-03-29 13:07**MOT test number** 700744609465**Result** ✓ Passed**MOT #5** 2017-03-29 09:37**MOT test number** 307591025501**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm worn on outer edge (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2016-05-18 08:03**MOT test number** 522064771709**Result** ✓ Passed**MOT #3** 2015-05-11 11:44**MOT test number** 616891935141**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #2** 2014-05-14 12:45**MOT test number** 288774834164**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-04-25 10:40**MOT test number** 806715413184**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
26 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	26 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	BX10USN
Plate since	2019-09-29
Current registration	BX10USN
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-28
Last registration	2023-06-27
Complete history	See info



Registration #1	2010-04-28	12 mi
Registration #2	2013-04-25	27.152 mi
Registration #3	2014-05-14	42.737 mi
Registration #4	2015-05-11	65.000 mi
Registration #5	2016-05-18	89.084 mi
Registration #6	2017-03-29	101.326 mi
Registration #7	2017-03-29	101.326 mi
Registration #8	2018-04-28	104.127 mi
Registration #9	2019-05-29	105.377 mi
Registration #10	2020-05-29	105.377 mi
Registration #11	2021-05-29	105.377 mi
Registration #12	2022-05-29	105.377 mi
Registration #13	2023-05-29	105.377 mi
Registration #14	2024-05-29	105.377 mi
Registration #15	2025-05-29	105.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2130 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	784551
---------------	--------