



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO HDI XTR
Colour	Grey
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

<b>MOT expiry date</b>	2025-01-09
<b>MOT pass rate</b>	77 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	7
<b>Total items failed</b>	9

<b>MOT #13</b>	2023-12-12 10:32
<b>MOT test number</b>	750815837635
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-01-09

<b>MOT #12</b>	2023-01-10 10:38
<b>MOT test number</b>	128820880942
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2022-02-10 16:45
<b>MOT test number</b>	219156798497
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2022-02-10 11:07
<b>MOT test number</b>	547717332245

<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
<b>Fail</b>	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Fail</b>	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
<b>Fail</b>	Offside Rear Direction indicator incorrect colour (4.4.3 (a))

**MOT #9** 2021-02-19 14:22**MOT test number** 631256786660**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**MOT #8** 2021-02-15 15:49**MOT test number** 968877564392**Result** ✗ Failed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front (5.3.4 (a) (i))**Fail** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #7** 2020-04-25 12:29**MOT test number** 589595792641**Result** ✓ Passed**MOT #6** 2019-05-03 12:31**MOT test number** 991132466474**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt All three rear seats**MOT #5** 2018-04-30 10:43**MOT test number** 146647393687**Result** ✓ Passed**Advice** Front Front brake pads low

**MOT #4** 2017-05-12 08:48**MOT test number** 442669341562**Result** ✓ Passed**Advice** Three child seats fitted to rear seats connotation fully check seat belts**MOT #3** 2016-05-27 12:17**MOT test number** 464552715663**Result** ✓ Passed**MOT #2** 2016-05-27 08:21**MOT test number** 216084197129**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Centre Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2015-07-01 14:00**MOT test number** 679302185166**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
9 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	9 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-08-28
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2012-08-28	8 mi
Registration #2	2015-07-01	12.982 mi
Registration #3	2016-05-27	24.780 mi
Registration #4	2016-05-27	24.780 mi
Registration #5	2017-05-12	29.483 mi
Registration #6	2018-04-30	34.444 mi
Registration #7	2019-05-03	39.378 mi
Registration #8	2020-04-25	43.779 mi
Registration #9	2020-05-20	45.277 mi
Registration #10	2020-05-20	45.277 mi
Registration #11	2020-05-20	45.277 mi
Registration #12	2020-05-20	45.277 mi
Registration #13	2020-05-20	45.277 mi
Registration #14	2020-05-20	45.277 mi
Registration #15	2020-05-20	45.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1426 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEV3012720