





report date: 2024-03-28

# General information

Make	VOLVO
Model	XC60 D4 R-DESIGN LUX NAV AWD
Colour	Black
Year of manufacture	2017
Top speed	124 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	187 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/11



YL66UFZ

report date: 2024-03-28

# Internet history

# Entry 1


Date 2021-06-04

Pictures 23

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2023-08-05
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #5	2022-08-06 08:51
MOT test number	449699043792
Result	<b>✓</b> Passed
Next expiry date	2023-08-05

MOT #4	2021-06-17 15:00
MOT test number	585930446608
Result	✓ Passed

MOT #3		2021-01-25 14:15
MOT test	number	378035304582
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/11



MOT #2 2021-01-25 10:29

MOT test number 701368603132

Result X Failed

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #1** 2020-01-17 16:11

**MOT test number** 899493403937

CarCheck.co.uk page 4/11



# Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	5 August 2023
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



## Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



## Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full research		
********		
***************************************		
***************************************		
	More info	
	More into	<b>&gt;</b>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NIE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



## Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-01-27
Last registration	2022-08-06
Complete history	See info



Registration #1	2017-01-27	9 mi
Registration #2	2020-01-17	48.732 mi
Registration #3	2021-01-25	59.483 mi
Registration #4	2021-01-25	59.483 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1867 kg
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number1734057