



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Grey
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-13
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-15
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	29
Total items failed	3

MOT #14	2023-06-12 08:05
MOT test number	740022105186
Result	✓ Passed
Next expiry date	2024-06-15
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2022-06-15 11:04

MOT test number

311682114470

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material union (1.1.11 (c))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material union (1.1.11 (c))
- Advice** Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2022-06-15 11:04

MOT test number

598815526115

Result**✗ Failed**

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material union (1.1.11 (c))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material union (1.1.11 (c))
- Advice** Nearside Front Outer Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #11

2021-06-16 10:28

MOT test number

688288595483

Result**✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #10** 2021-06-15 13:40**MOT test number** 184951791801**Result** ✗ Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9 2020-07-21 10:03**MOT test number** 896703015993**Result** ✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #8 2019-07-23 08:45**MOT test number** 739185472697**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2018-07-11 07:40**MOT test number** 898839540909**Result** ✓ Passed**MOT #6** 2017-06-27 08:39**MOT test number** 728460494785**Result** ✓ Passed**MOT #5** 2016-06-29 08:06**MOT test number** 798470741070**Result** ✓ Passed



MOT #4	2015-06-30 09:12
MOT test number	347951985140
Result	✓ Passed
MOT #3	2014-07-01 09:24
MOT test number	725692184132
Result	✓ Passed
MOT #2	2013-07-24 15:39
MOT test number	416605603216
Result	✓ Passed
MOT #1	2013-05-23 10:53
MOT test number	667863343152
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
15 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 ND10GTU
Plate since	2019-03-28
Current registration	 ND10GTU
Plate since	2019-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-13
Last registration	2023-06-12
Complete history	See info



Registration #1	2010-07-13	27 mi
Registration #2	2013-05-23	31.859 mi
Registration #3	2013-07-24	33.934 mi
Registration #4	2014-07-01	36.718 mi
Registration #5	2015-06-30	40.141 mi
Registration #6	2016-06-29	44.254 mi
Registration #7	2017-06-27	47.837 mi
Registration #8	2018-07-11	51.829 mi
Registration #9	2019-06-29	55.277 mi
Registration #10	2020-06-29	58.277 mi
Registration #11	2021-06-29	61.277 mi
Registration #12	2022-06-29	64.277 mi
Registration #13	2023-06-29	67.277 mi
Registration #14	2024-06-29	70.277 mi
Registration #15	2025-06-29	73.277 mi
Registration #16	2026-06-29	76.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843