





report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI EXCLUSIVE
Colour	Silver
Year of manufacture	2010
Top speed	114 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-21

Pictures 38

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



WM10KCY report date: 2024-03-28

MOT history

MOT expiry date	2024-06-26
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	34
Total items failed	16

MOT #17		2023-06-27 15:12
MOT test	number	497252160772
Result		✓ Passed
Next expi	ry date	2024-06-26
Advice	Central Rear Seat belt buckle slightly damaged functions ok (7.1.2 (d))	
Advice	Front Seat belt buckle slightly damaged both - functions ok (7.1.2 (d))	

MOT #16		2022-06-23 12:11
MOT test	number	576852374393
Result		✓ Passed
Advice	Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))	
Advice	Offside Front Seat belt buckle slightly damaged (7.1.2 (d))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge bald edge (5.2.3 (e))	

MOT #15	2021-06-18 13:20
MOT test number	746357206680
Result	✓ Passed

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT test number

Fesult

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Advice
(a) (i))

Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4)

MOT test number
742657496028

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Child Seat fitted not allowing full inspection of adult belt

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12

MOT test number

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT test number

Result

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT test number

Result

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

327065181236

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Dashboard indicates service due.

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Diesel additive tank leaking

MOT #8 2017-03-08 17:10 567832735910 **MOT** test number Result × Failed Pass with rectification Offside Headlamp not working on dipped beam Bulb replaced PRS (1.7.5a) Fail Offside Registration plate lamp not working (1.1.C.1d) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Diesel additive tank leaking Fail Nearside Registration plate lamp not working (1.1.C.1d) Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.4.G.2) **Advice** Dashboard indicates service due. **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #7 2016-03-15 16:09

MOT test number 295938647548

Result ✓ Passed

Advice Offside front daytime running light not working

Advice Oil leak noted

Advice Child seats fitted to offside, centre & nearside rear seats- cannot inspect adult belts fully

MOT #6 2016-03-14 12:28

MOT test number 928628075126

Result X Failed

Advice Child seats fitted to offside, centre & nearside rear seats- cannot inspect adult belts fully

Fail Nearside Front coil spring broken (2.4.C.1a)

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Offside front daytime running light not working

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Oil leak noted

MOT #5 2015-03-17 09:13

MOT test number 495046175043

Result

Passed

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #4 2015-01-30 16:46 **MOT** test number 888550535065 Result × Failed **Notice** Rear fog lamp cracked not iluminating white light Fail Nearside Rear Tyre(s) incorrect because a lightweight or space saving wheel is fitted (4.1.A.1b) **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice O/S/R tyre perishing 215 55 16 **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3

MOT test number

Result

Notice Both rear tyres wearing low

2014-07-11 14:32

✓ Passed

MOT #2 2014-07-10 10:59 **MOT** test number 758991494183 Result × Failed Fail Seat belt retracting mechanism defective (5.2.5b) Fail Offside Rear Mechanical brake component has restricted free movement (3.5.1k) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Rear Mechanical brake component has restricted free movement (3.5.1k) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Notice** Both rear tyres wearing low

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #1 2013-07-02 10:57

MOT test number 226833383471

Result ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	26 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIN
Plate since	
	More info

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-30
Last registration	2023-06-27
Complete history	See info



Registration #1	2010-06-30	25 mi
Registration #2	2013-07-02	21.142 mi
Registration #3	2014-07-10	26.019 mi
Registration #4	2014-07-11	26.019 mi
Registration #5	2015-01-30	28.326 mi
Registration #6	2015-03-17	28.369 mi
Registration #7	2016-03-14	44.468 mi
Registration #8	2016-03-15	44.469 mi
Registration #9	2017-03-08	56.906 mi
Designation #10	2017-03-09	56.907 mi
Registration #10	2017-03-09	30.307 1111
Registration #10	2017-03-09	30.307 111
_	2017-03-09	30.307 1111
Registration #11	2017-03-09	30.307 1111
Registration #11 Registration #12	2017-03-09	30.307 111
Registration #11 Registration #12 Registration #13	2017-03-09	30.307 1111
Registration #11 Registration #12 Registration #13 Registration #14	2017-03-09	30.307 1111
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2017-03-09	30.307 1111
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2017-03-09	30.307 1111
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2017-03-09	

More info >

CarCheck.co.uk page 14/15



WM10KCY report date: 2024-03-28

Car features

S0225	Air conditionir
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1837 mm
Height	1640 mm
Length	4365 mm
Wheel base	2613 mm
Kerb weight	1590 kg
Max. allowed weight	2030 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 15/15

JBCJ3017162