



report date: 2024-03-29

General information

Make	KIA
Model	CARENS LS CRDI
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg





LABEL UNKNOWN



Internet history

Entry 2





Date	2021-09-16
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-25
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #17</b>	2021-12-16 11:45
<b>MOT test number</b>	677411519676
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-12-16
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Minor</b>	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #16</b>	2020-12-17 12:10
<b>MOT test number</b>	567417240574
<b>Result</b>	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #15</b>	2019-06-03 10:32
<b>MOT test number</b>	936451626466
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
<b>Advice</b>	Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

<b>MOT #14</b>	2018-06-05 13:54
<b>MOT test number</b>	665485196116
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #13** 2017-06-17 16:19**MOT test number** 667465625681**Result** ✓ Passed**MOT #12** 2017-06-17 12:42**MOT test number** 375148379698**Result** ✗ Failed**Advice** Nearside front tyre worn on inner edge**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #11** 2016-04-07 13:44**MOT test number** 833351410822**Result** ✓ Passed**MOT #10** 2016-04-07 09:58**MOT test number** 178421709634**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #9** 2015-04-01 12:16**MOT test number** 776841395053**Result** ✓ Passed

**MOT #8** 2015-03-31 15:02**MOT test number** 606020095006**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2014-04-01 17:03**MOT test number** 849571594039**Result** ✓ Passed**MOT #6** 2013-10-09 14:56**MOT test number** 986252283209**Result** ✓ Passed**Notice** Rear tyres worn on the inside edge**Notice** Front reg plate cracked**MOT #5** 2013-10-09 14:56**MOT test number** 499652783203**Result** ✗ Failed**Notice** Rear tyres worn on the inside edge**Notice** Front reg plate cracked**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2012-11-08 09:58**MOT test number** 675993812361**Result** ✓ Passed**Notice** Uneven wear on the rear tyres**MOT #3** 2011-11-03 10:08**MOT test number** 126647201306**Result** ✓ Passed**Advice** Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2010-11-01 11:26**MOT test number** 730535200386**Result** ✓ Passed**Notice** O/s wiper split**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #1** 2009-11-05 11:28**MOT test number** 290259509320**Result** ✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-08
Last registration	2021-12-16
Complete history	<a href="#">See info</a>



Registration #1	2006-11-08	12 mi
Registration #2	2009-11-05	28.188 mi
Registration #3	2010-11-01	37.609 mi
Registration #4	2011-11-03	46.680 mi
Registration #5	2012-11-08	56.433 mi
Registration #6	2013-10-09	63.305 mi
Registration #7	2014-04-01	66.619 mi
Registration #8	2015-03-31	86.063 mi
Registration #9	2015-04-01	86.065 mi
Registration #10	2016-04-07	104.203 mi
Registration #11	2016-04-07	104.203 mi
Registration #12	2016-04-07	104.203 mi
Registration #13	2016-04-07	104.203 mi
Registration #14	2016-04-07	104.203 mi
Registration #15	2016-04-07	104.203 mi
Registration #16	2016-04-07	104.203 mi
Registration #17	2016-04-07	104.203 mi
Registration #18	2016-04-07	104.203 mi
Registration #19	2016-04-07	104.203 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1657 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	D4EA6H24489