




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-02
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-10-02
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	31
Total items failed	5

MOT #18 2023-10-03 11:35**MOT test number** 411854044337**Result** ✓ Passed**Next expiry date** 2024-10-02**Advice** Front Exhaust has a minor leak of exhaust gases flexible down pipe slightly blowing (6.1.2 (a))**Advice** Offside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement
dust cover slight split (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2023-10-03 11:35**MOT test number** 796515991110**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Front Windscreen wiper blade missing not working wiper arm not
moving (3.4 (b) (ii))**Advice** Offside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement
dust cover slight split (5.3.4 (a) (i))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Exhaust has a minor leak of exhaust gases flexible down pipe slightly blowing (6.1.2 (a))

**MOT #16** 2022-09-30 17:03**MOT test number** 566319282585**Result** ✓ Passed**MOT #15** 2022-09-30 17:03**MOT test number** 251948132940**Result** ✗ Failed

Pass with rectification Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Position lamp not working (4.2.1 (a) (ii))

MOT #14 2021-10-02 12:38**MOT test number** 334520139347**Result** ✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))

MOT #13 2021-10-01 11:47**MOT test number** 218177794114**Result** ✗ Failed

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2020-09-14 12:31

MOT test number

796259572714

Result

✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases Flexi pipe (6.1.2 (a))
- Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge cracking/perishing also. (5.2.3 (e))
- Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2019-08-28 11:47

MOT test number

619913044812

Result

✓ Passed

- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Both sides shack absorbers have corrosion to the casing

MOT #10

2019-08-28 09:50

MOT test number

913800709586

Result

✗ Failed

- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Both sides shack absorbers have corrosion to the casing
- DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #9** 2018-09-08 08:16**MOT test number** 691332067470**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2017-09-11 12:08**MOT test number** 279249992694**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2016-09-10 11:20**MOT test number** 137970783793**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-09-04 08:50**MOT test number** 453004575694**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-09-13 09:49**MOT test number** 149426454209**Result** ✓ Passed**MOT #4** 2013-09-09 10:03**MOT test number** 665732953242**Result** ✓ Passed



MOT #3	2012-09-11 12:06
MOT test number	569735952209
Result	✓ Passed
MOT #2	2011-08-26 11:52
MOT test number	939468031225
Result	✓ Passed
MOT #1	2010-09-06 13:37
MOT test number	342919040235
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
2 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	2015-01-01
Owner 2	2015-01-01
Owner 3	2015-01-01
Owner 4	2015-01-01
Owner 5	2015-01-01
Owner 6	2015-01-01

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VAUXH
Plate since	2015-01-01
Current registration	VAUXH
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-13
Last registration	2023-10-03
Complete history	See info



Registration #1	2007-09-13	12 mi
Registration #2	2010-09-06	4.483 mi
Registration #3	2011-08-26	6.668 mi
Registration #4	2012-09-11	7.983 mi
Registration #5	2013-09-09	12.278 mi
Registration #6	2014-09-13	22.653 mi
Registration #7	2015-09-04	31.827 mi
Registration #8	2016-09-10	41.028 mi
Registration #9	2017-09-11	51.015 mi
Registration #10	2018-09-08	61.350 mi
Registration #11	2019-09-08	71.777 mi
Registration #12	2020-09-08	82.204 mi
Registration #13	2021-09-08	92.631 mi
Registration #14	2022-09-08	103.058 mi
Registration #15	2023-09-08	113.485 mi
Registration #16	2024-09-08	123.912 mi
Registration #17	2025-09-08	134.339 mi
Registration #18	2026-09-08	144.766 mi
Registration #19	2027-09-08	155.193 mi
Registration #20	2028-09-08	165.620 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118