



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT 5 STR
Colour	Blue
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





## MOT history

MOT expiry date	2020-10-30
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	24
Total items failed	4

MOT #10 2019-05-01 14:27

MOT test number 773683336109

Result ✓ Passed

Next expiry date 2020-10-30

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Corrosion on chassis, both sides.
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #9 2019-05-01 12:37

MOT test number 244905687953

Result ✗ Failed

- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Rear Corrosion on chassis, both sides.
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2018-06-04 15:52**MOT test number** 823113680859**Result** ✓ Passed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MOT #7** 2018-06-04 15:52**MOT test number** 209537217921**Result** ✗ Failed**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MOT #6** 2017-05-15 15:33**MOT test number** 105091793841**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Unable to see brake fluid level clearly.**MOT #5** 2016-05-11 13:18**MOT test number** 514353073436**Result** ✓ Passed

**MOT #4** 2015-03-27 10:48**MOT test number** 246326485086**Result** ✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Shock absorber has a slightly worn bush (2.7.4)

**MOT #3** 2014-04-10 10:45**MOT test number** 287920604424**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)

**MOT #2** 2013-03-27 15:08**MOT test number** 187486783442**Result** ✓ Passed

- Notice** Both rear seats folded flat and boot full unable to test belts etc

**MOT #1** 2012-04-04 15:39**MOT test number** 848245592027**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
2 October 2019

X

MOT

Expired:  
30 October 2020

Tax status	Expired at 2 October 2019
Days left	1672 days too late
MOT expiry date	30 October 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>VU09BAO</b>
Plate since	2019-06-29
Current registration	<b>VU09BAO</b>
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-04-20
Last registration	2019-05-01
Complete history	<a href="#">See info</a>



Registration #1	2009-04-20	13 mi
Registration #2	2012-04-04	60.743 mi
Registration #3	2013-03-27	80.707 mi
Registration #4	2014-04-10	105.684 mi
Registration #5	2015-03-27	127.419 mi
Registration #6	2016-05-11	135.892 mi
Registration #7	2017-05-01	151.277 mi
Registration #8	2018-05-01	166.662 mi
Registration #9	2019-05-01	182.047 mi
Registration #10	2020-05-01	197.432 mi
Registration #11	2021-05-01	212.817 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007