




report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 16V
Colour	Grey
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	256 BHP
Max. torque	380 Nm at 3.000 rpm
Engine capacity	2.261 cc
Cylinders	4
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	34.9 mpg
Consumption combined	27.7 mpg
CO2 emission	243 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-07
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-05
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	57
Total items failed	11

MOT #19	2023-12-20 12:04
MOT test number	776050818853
Result	✓ Passed
Next expiry date	2025-01-05

MOT #18	2023-12-19 11:08
MOT test number	568544677019
Result	✗ Failed
<p>MAJOR Offside Headlamp aim projected beam image is obviously incorrect no beam pattern o/s (4.1.2 (c))</p> <p>MAJOR Nearside Rear Parking brake inoperative on one side (1.4.1 (a))</p> <p>MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))</p> <p>DANGEROUS Nearside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))</p>	



MOT #17

2023-01-06 14:32

MOT test number

963722535703

Result		✓ Passed
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Handbrake lever travel high	
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))	
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Engine bay covers and under-trays fitted obscuring some components	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Both rear tyres cracking in tread	

**MOT #16**

2023-01-06 11:20

MOT test number

186053789519

Result**✗ Failed**

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure (6.1.7 (g) (ii))

Advice Engine bay covers and under-trays fitted obscuring some components

Advice Offside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))

Advice Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Both rear tyres cracking in tread

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MAJOR Offside Front Headlamp levelling device inoperative (4.1.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge (5.2.3 (e))

Advice Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Handbrake lever travel high

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MAJOR Nearside Front Headlamp levelling device inoperative (4.1.5 (a))

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #15

2021-08-25 15:10

MOT test number

186392329861

Result**✓ Passed**

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14** 2020-10-19 08:14**MOT test number** 509326991866**Result** ✓ Passed**MOT #13** 2019-11-07 09:22**MOT test number** 508763471447**Result** ✓ Passed

- Advice** Under trays fitted obscuring some components
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #12 2018-11-19 09:12**MOT test number** 268284230805**Result** ✓ Passed

- Advice** Under trays fitted obscuring some components
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced rear of inner sills (6.1.1 (c) (i))

**MOT #11**

2018-11-15 10:31

MOT test number

897780402861

Result**✗ Failed****MAJOR** Brake performance not tested (1.2.1 (g))**DANGEROUS** Offside Front Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced rear of sills on inner and rear and front cross members (6.1.1 (c) (i))**Advice** Tyre worn close to legal limit/worn on edge all 4 tyres n/s/f/o/s/f/n/s/r/o/s/r (5.2.3 (e))**DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #10**

2017-11-02 16:23

MOT test number

258085893938

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2017-11-02 11:53

MOT test number

964274661999

Result**✗ Failed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)



MOT #8	2016-11-18 14:52
---------------	------------------

MOT test number	855675703123
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2015-11-20 11:52
---------------	------------------

MOT test number	715260319598
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2014-12-12 11:44
---------------	------------------

MOT test number	449776944486
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

MOT #5	2013-12-12 16:07
---------------	------------------

MOT test number	928586843346
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

**MOT #4** 2013-12-12 12:11**MOT test number** 946046243312**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front front brake binding (3.7.B.1)**Fail** Offside Front Anti-roll bar linkage synthetic bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Rear Anti-roll bar linkage synthetic bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front front brake binding (3.7.B.1)**Fail** Nearside Rear Anti-roll bar linkage synthetic bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #3** 2012-12-13 15:19**MOT test number** 356238542358**Result** ✓ Passed**MOT #2** 2012-12-06 12:02**MOT test number** 415991342390**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Notice** Front discs in poor condition on inner faces



MOT #1	2011-12-16 16:06
MOT test number	337380851392
Result	✓ Passed
Notice	Oil leak
Notice	Front discs in poor condition on inner faces



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 January 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	5 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	ST58KHD
Plate since	2019-09-29
Current registration	ST58KHD
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-12-18
Last registration	2023-12-20
Complete history	See info



Registration #1	2008-12-18	27 mi
Registration #2	2011-12-16	11.273 mi
Registration #3	2012-12-06	13.883 mi
Registration #4	2012-12-13	13.963 mi
Registration #5	2013-12-12	18.124 mi
Registration #6	2013-12-12	18.124 mi
Registration #7	2014-12-12	21.964 mi
Registration #8	2015-11-20	25.008 mi
Registration #9	2016-11-18	27.697 mi
Registration #10	2017-11-02	38.451 mi
Registration #11	2017-11-02	38.541 mi
Registration #12	2018-11-02	38.541 mi
Registration #13	2018-11-02	38.541 mi
Registration #14	2018-11-02	38.541 mi
Registration #15	2018-11-02	38.541 mi
Registration #16	2018-11-02	38.541 mi
Registration #17	2018-11-02	38.541 mi
Registration #18	2018-11-02	38.541 mi
Registration #19	2018-11-02	38.541 mi
Registration #20	2018-11-02	38.541 mi
Registration #21	2018-11-02	38.541 mi

More info >



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4680 mm
Wheel base	2750 mm
Kerb weight	1695 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L3 20279163