



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	White
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-19
Pictures	2
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT #13	2023-04-03 14:31
MOT test number	839731317228
Result	✓ Passed
Next expiry date	2024-04-02
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre

MOT #12	2023-03-29 13:09
MOT test number	865332787843
Result	✗ Failed
Fail	Front Position lamp not working Both (4.2.1 (a) (ii))
Advice	Nearside Rear Nail in tyre
Fail	Nearside Front Service brake excessively binding (1.2.1 (f))
Fail	Rear Registration plate inscription illegible (0.1 (b))
Fail	Nearside Headlamp light intensity severely reduced (4.1.4 (a))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on edge (5.2.3 (e))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #11	2022-02-28 16:31
MOT test number	426100226968
Result	✓ Passed

MOT #10	2019-11-11 16:34
MOT test number	623669256274
Result	✓ Passed

**MOT #9** 2019-11-09 10:34**MOT test number** 524600562048**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #8** 2018-11-14 14:42**MOT test number** 177522729857**Result** ✓ Passed**MOT #7** 2018-05-14 10:01**MOT test number** 488323053442**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2017-05-08 09:32**MOT test number** 732886861128**Result** ✓ Passed**MOT #5** 2016-05-21 11:13**MOT test number** 370437281876**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-05-21 09:42**MOT test number** 528151345178**Result** ✓ Passed



MOT #3	2014-05-23 10:15
MOT test number	926723644166
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #2	2014-05-23 10:15
MOT test number	808563044161
Result	✓ Passed

MOT #1	2013-05-20 17:29
MOT test number	978310343141
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-05-22
Last registration	2023-04-03
Complete history	<a href="#">See info</a>



Registration #1	2010-05-22	22 mi
Registration #2	2013-05-20	24.164 mi
Registration #3	2014-05-23	46.214 mi
Registration #4	2015-05-21	65.209 mi
Registration #5	2016-05-21	70.316 mi
Registration #6	2017-05-08	77.145 mi
Registration #7	2018-05-14	81.108 mi
Registration #8	2019-05-22	85.277 mi
Registration #9	2020-05-22	89.277 mi
Registration #10	2021-05-22	93.277 mi
Registration #11	2022-05-22	97.277 mi
Registration #12	2023-05-22	101.277 mi
Registration #13	2024-05-22	105.277 mi
Registration #14	2025-05-22	109.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	957553