





## General information

Make	MERCEDES
Model	S-Class S600L
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	4.6 seconds
Gearbox	5 speed automatic

# Engine & fuel consumption

Power	517 BHP
Max. torque	830 Nm at 1.800 rpm
Engine capacity	5.513 cc
Cylinders	12
Fuel type	Petrol
Consumption city	13.1 mpg
Consumption extra urban	29.1 mpg
Consumption combined	20.0 mpg
CO2 emission	340 g/km
CO2 label	М







# Internet history

Entry 2	
Date	2021-07-17
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-07-16
Pictures	50
Listing price	View report



source: autotrader.co.uk









# MOT history

MOT expiry date	2022-04-08
MOT pass rate	100 %
MOT passed	11
Failed MOT tests	0
Total advice items	11
Total items failed	0

MOT #11	2021-04-09 09:32
MOT test number	205074629694
Result	✓ Passed
Next expiry date	2022-04-08

MOT #10		2020-01-10 10:36
MOT test	number	523414837801
Result		🗸 Passed
Advice	Front Brake pipe corroded, covered in grease or other material both slight (1.1.11	(c))
Advice	Front Brake pipe corroded, covered in grease or other material both slight (1.1.11	(c))

MOT #9	2018-09-17 15:08
MOT test number	802879949028
Result	✓ Passed
МОТ #8	2018-01-18 12:19
MOT test number	424746610936
Result	✓ Passed

MOT #7	2017-01-10 12:20
MOT test number	485383174946
Result	✓ Passed





MOT #6		2016-01-12 16:09
MOT test	number	482844527176
Result		✓ Passed
MOT #5		2015-01-20 12:28
MOT test	number	498540125079
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Torque/reaction arm has a slightly deteriorated rub	ober bush (2.4.G.2)
мот #4		2013-12-10 16:08

MOT #4	2013-12-10 16:08	
MOT test number	367214143300	
Result	✓ Passed	
Notice Near side raer tyer has cut		
<b>Advice</b> Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)		
Notice Near side front tyre has cut on side wall		
<b>Notice</b> Off side front tyer has cut		

MOT #3		2013-05-23 16:07
MOT test	number	238973843119
Result		✓ Passed
Notice	Offside front tyre cuts in outer side wall	
Notice	Nearside front tyre a cut in outer side wall	

MOT #2	2011-12-07 13:28
MOT test number	276151941385
Result	✓ Passed





MOT #1	2010-12-16 13:59
MOT test number	583120850323
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 31 March 2022	<b>X</b> <b>MOT</b> Expired: 8 April 2022
Tax status	Expired at 31 March 2022
Days left	759 days too late
MOT expiry date	8 April 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	Μ
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	AAMP
Туре	
Damage 2	AMPLE
Date	
Category	ANPLE .
Туре	We have a state of the state of
. ) P =	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
**********	
And a second s	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-12-17
Last registration	2021-04-09
Complete history	See info



Registration #1	2007-12-17	8 mi
Registration #2	2010-12-16	15.169 mi
Registration #3	2011-12-07	16.243 mi
Registration #4	2013-05-23	20.046 mi
Registration #5	2013-12-10	21.270 mi
Registration #6	2015-01-20	22.642 mi
Registration #7	2016-01-12	23.052 mi
Registration #8		10.200 est
5		
Registration #9		11.777 esi
-		10.000 est 10.000 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		01.000 est 01.000 est 01.000 est 01.000 est 01.000 est

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1871 mm
Height	1485 mm
Length	5226 mm
Wheel base	3165 mm
Kerb weight	2090 kg
Additional information	
Fuel tank capacity	90
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
	5