




General information

Make	JAGUAR
Model	XJ V8 SE
Colour	Grey
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	6.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	420 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	17.7 mpg
Consumption extra urban	34.9 mpg
Consumption combined	26.0 mpg
CO2 emission	264 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-06-13
Pictures	3
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-07
MOT pass rate	53 %
MOT passed	16
Failed MOT tests	14
Total advice items	28
Total items failed	25

MOT #30 2023-03-13 17:30

MOT test number 747834388282

Result ✓ Passed

Next expiry date 2024-04-07

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #29 2022-04-06 07:07

MOT test number 889002424919

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #28** 2021-04-08 09:40**MOT test number** 427428448568**Result** ✓ Passed**MOT #27** 2021-04-08 09:40**MOT test number** 456531814111**Result** ✗ Failed**Pass with rectification** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #26** 2019-11-06 13:52**MOT test number** 810701292404**Result** ✓ Passed**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #25** 2019-11-04 12:37**MOT test number** 310186368581**Result** ✗ Failed**Fail** Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #24** 2018-10-25 09:39**MOT test number** 618690109073**Result** ✓ Passed**MOT #23** 2018-10-25 09:39**MOT test number** 193997551588**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))

**MOT #22** 2017-11-03 10:36**MOT test number** 982580019088**Result** ✓ Passed**Advice** Under body covers fitted**Advice** Offside Front Wheel bearing/hub assembly has slight play**MOT #21** 2017-10-30 14:27**MOT test number** 186755540405**Result** ✗ Failed**Advice** Under body covers fitted**Fail** Nearside Rear Upper Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Wheel bearing/hub assembly has slight play**Fail** Offside Rear Lower Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Rear Lower Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #20** 2016-10-29 08:45**MOT test number** 812794522192**Result** ✓ Passed**MOT #19** 2016-10-29 08:45**MOT test number** 770005328091**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #18** 2015-11-13 11:27**MOT test number** 609438331360**Result** ✓ Passed

**MOT #17** 2015-11-13 10:11**MOT test number** 521472264472**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #16** 2014-11-10 16:34**MOT test number** 907464214331**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #15** 2014-11-10 16:34**MOT test number** 779924114381**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #14** 2014-06-26 12:41**MOT test number** 675397574142**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**MOT #13** 2013-06-03 14:10**MOT test number** 248954853411**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2013-06-03 12:48**MOT test number** 527484453181**Result** ✗ Failed**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #11** 2012-11-15 16:17**MOT test number** 257460422338**Result** ✗ Failed**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #10** 2012-01-16 10:39**MOT test number** 208706212093**Result** ✓ Passed

**MOT #9** 2010-11-11 11:31**MOT test number** 480095510361**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #8** 2010-11-11 11:31**MOT test number** 644035410362**Result** ✓ Passed**MOT #7** 2009-11-23 15:58**MOT test number** 282957829394**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2009-11-23 15:58**MOT test number** 573937629377**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2008-11-20 14:09**MOT test number** 794225228388**Result** ✓ Passed

**MOT #4** 2008-11-20 14:09**MOT test number** 151275028337**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2007-06-13 15:11**MOT test number** 914684867137**Result** ✓ Passed**Notice** Near side tyre wearing on inner edge**MOT #2** 2007-06-12 17:05**MOT test number** 254453567148**Result** ✗ Failed**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Notice** Near side front tyre wearing on inner edge**MOT #1** 2006-06-01 11:38**MOT test number** 813552656120**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history


Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2003-04-16
Last registration	2023-03-13
Complete history	See info



Registration #1	2003-04-16	6 mi
Registration #2	2006-06-01	15.500 mi
Registration #3	2007-06-12	25.132 mi
Registration #4	2007-06-13	25.132 mi
Registration #5	2008-11-20	35.269 mi
Registration #6	2009-11-23	44.064 mi
Registration #7	2010-11-11	51.491 mi
Registration #8	2012-01-16	58.800 mi
Registration #9	2012-11-15	61.381 mi
Registration #10	2013-06-03	63.806 mi
Registration #11	2013-06-03	63.806 mi
Registration #12	2014-06-26	70.418 mi
Registration #13	2014-11-10	71.386 mi
Registration #14	2015-11-13	77.097 mi
Registration #15	2016-06-03	81.317 mi
Registration #16	2016-06-03	81.317 mi
Registration #17	2016-06-03	81.317 mi
Registration #18	2016-06-03	81.317 mi
Registration #19	2016-06-03	81.317 mi
Registration #20	2016-06-03	81.317 mi
Registration #21	2016-06-03	81.317 mi
Registration #22	2016-06-03	81.317 mi
Registration #23	2016-06-03	81.317 mi
Registration #24	2016-06-03	81.317 mi
Registration #25	2016-06-03	81.317 mi
Registration #26	2016-06-03	81.317 mi

Registration #27	2023-05-20	20,000,000
Registration #28	2023-05-20	20,000,000

More info >



Dimensions & weight

Width	2108 mm
Height	1448 mm
Length	5090 mm
Wheel base	3034 mm
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	85 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	0311190403SB