





report date: 2024-03-29

### General information

Make	FORD
Model	TRANSIT 280 MWB SHR P/V 85
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/13




# Internet history

### Entry 1

Date 2021-09-25

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



# MOT history

MOT expiry date	2025-04-21
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	11
Total items failed	13

MOT #16		2024-04-22 12:09
MOT test	number	591392397471
Result		✓ Passed
Next expi	ry date	2025-04-21
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre	

MOT #15	2024-04-15 10:44
MOT test number	129605417771
Result	🗙 Failed
Fail Windscreen washer not working (3.5 (a))	
Advice Nearside Rear Nail in tyre	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Fail Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)	))
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))	

CarCheck.co.uk page 3/13



Result

AJ11NPE report date: 2024-03-29

✓ Passed

**MOT #14** 2023-02-21 14:26

MOT test number 108045151818

**MOT #13** 2023-02-17 13:30

MOT test number 660971319691

Result X Failed

Fail Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Fail Nearside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))

Fail Windscreen washer not working (3.5 (a))

**MOT #12** 2022-01-25 16:42

MOT test number 496363821013

Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #11** 2022-01-25 16:42

**MOT test number** 348231248757

Result X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps both side (4.7.2 (a))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/13



**MOT** test number

AJ11NPE report date: 2024-03-29

984258799337

 MOT #10
 2021-02-24 10:12

 MOT test number
 437658164031

 Result
 ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9

MOT test number

516645249222

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

MOT #8 2020-03-14 11:31 MOT test number 344866001028

**Result** ✓ Passed

**MOT #7** 2019-03-08 10:02

**MOT test number** 710179621497

Result \( \sqrt{Passed} \)

MOT #6 2018-03-17 10:51

Result Passed

MOT #5 2018-03-17 10:51

**MOT test number** 348318590889

**Result** X Failed

Pass with rectification Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

**Pass with rectification** Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 5/13



MOT #4 2017-03-23 17:17 **MOT test number** 200679223427 Result ✓ Passed 2016-09-07 11:28 MOT #3 **MOT test number** 708718009356 Result ✓ Passed MOT #2 2015-09-19 13:07 **MOT test number** 340873562154 Result ✓ Passed MOT #1 2014-06-27 16:51 246358274416 **MOT test number** Result ✓ Passed **Advice** Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



#### Tax & MOT check





Tax status Expired at 1 July 2023

Days left 303 days too late

MOT expiry date 21 April 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
HARMAN CONTRACTOR CONT	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-07-06
Last registration	2024-04-22
Complete history	See info



Registration #1	2011-07-06	14 mi
Registration #2	2014-06-27	32.521 mi
Registration #3	2015-09-19	50.597 mi
Registration #4	2016-09-07	63.641 mi
Registration #5	2017-03-23	68.262 mi
Registration #6	2018-03-17	77.637 mi
Registration #7	2018-03-17	77.637 mi
Registration #8	2019-03-08	86.712 mi
Registration #9	2020-03-14	95.875 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



### Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	2360 mm
Height	2532 mm
Length	5230 mm
Max. allowed weight	2800 kg

# Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	BY63554

CarCheck.co.uk page 13/13