




report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	Grey
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-01
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-15
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	35
Total items failed	3

MOT #20	2024-02-10 13:07
MOT test number	752909050308
Result	✓ Passed
Next expiry date	2025-02-15

MOT #19	2023-01-30 12:55
MOT test number	454694148027
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18	2023-01-30 10:29
MOT test number	317874521794
Result	✗ Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-02-07 11:32
MOT test number	668679284064
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge Both Sides (5.2.3 (e))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16** 2022-02-07 11:32**MOT test number** 307517912429**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge Both Sides (5.2.3 (e))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #15** 2021-02-06 10:10**MOT test number** 384662104682**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #14** 2020-02-01 09:48**MOT test number** 492986706232**Result** ✓ Passed**MOT #13** 2019-02-16 14:36**MOT test number** 737043566896**Result** ✓ Passed**MOT #12** 2019-02-14 15:04**MOT test number** 643332282647**Result** ✗ Failed**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #11**

2019-01-18 12:35

MOT test number

799047603702

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MAJOR Power steering pump leaking (2.1.5 (a))

MOT #10

2018-08-28 15:26

MOT test number

755097948550

Result**✓ Passed**

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2018-08-24 14:44

MOT test number

530542961960

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Exhaust has a major leak of exhaust gases CAT FLEXI SECTION (6.1.2 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #8

2017-08-11 15:00

MOT test number

547772805373

Result**✓ Passed****MOT #7**

2017-08-10 12:28

MOT test number

328161793020

Result**✗ Failed**

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #6

2016-08-09 12:07

MOT test number

263137570545

Result**✓ Passed**

Advice Front tyres wearing on inner edges



MOT #5	2015-08-13 09:40
---------------	------------------

MOT test number	196885625260
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-08-06 10:10
---------------	------------------

MOT test number	956928614233
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Slight splitting front wishbones rear bushes
---------------	--

MOT #3	2013-08-16 15:00
---------------	------------------

MOT test number	519858223229
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-08-28 16:49
---------------	------------------

MOT test number	779541642236
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2012-01-26 12:23
---------------	------------------

MOT test number	698466722064
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 November
Days left	186
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-10-06
Last registration	2024-02-10
Complete history	See info



Registration #1	2008-10-06	22 mi
Registration #2	2012-01-26	32.014 mi
Registration #3	2012-08-28	38.002 mi
Registration #4	2013-08-16	40.724 mi
Registration #5	2014-08-06	43.936 mi
Registration #6	2015-08-13	46.758 mi
Registration #7	2016-08-09	49.629 mi
Registration #8	2017-08-10	52.411 mi
Registration #9	2017-08-11	52.412 mi
Registration #10	2018-08-24	69.785 mi
Registration #11	2018-08-28	69.866 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi
Registration #21	2019-05-20	75.277 mi
Registration #22	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1289 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	153102