





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-31	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



YR62PPX report date: 2024-03-28

MOT history

MOT expiry date	2025-03-08
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	15
Total items failed	9

MOT #15	2024-02-29 13:17
MOT test number	940336467448
Result	✓ Passed
Next expiry date	2025-03-08

MOT #14		2023-03-09 09:59
MOT test	number	659758408435
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))	

MOT #13	2023-02-03 12:02
MOT test number	107057170231
Result	× Failed
Advice N/S/R Tyre worn close to the legal limit.	
Advice O/S/R Tyre worn.	
Fail Nearside Side repeater light intensity significantly reduced (4.4.3 (a))	

MOT #12	2022-02-07 13:48
MOT test number	839405358623
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2022-02-02 14:49

MOT test number 875757274996

Result

X Failed

Fail

Nearside Front Tyre tread depth below requirements of 1.6mm badly worn on the inner edge (5.2.3 $\,$

(e))

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10 2021-02-01 15:48

MOT test number 338975944301

Result
✓ Passed

MOT #9 2021-02-01 11:07

MOT test number 192977481143

Result X Failed

Advice

Brake disc worn, pitted or scored, but not seriously weakened front (1.1.14 (a) (ii))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2020-07-24 09:02

MOT test number 338692822926

Result

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

770899452629

MOT #7 2020-07-21 16:19

MOT test number 353627911746

Result X Failed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Nearside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Advice Nearside Rear Nail in tyre

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Advice Offside Rear Nail in tyre

MOT test number

MOT #6 2020-02-18 17:00

MOT test number 106093318465

Result
✓ Passed

MOT #5 2020-02-18 09:56

Result X Failed

Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #4 2019-01-18 11:09

MOT test number 736500504497

Result

Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Nail in tyre

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Fesult

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2

MOT test number

2017-01-26 12:36

MOT test number

211128821611

Result

Advice

Nearside Front Tyre worn close to the legal limit wearing close to limit on outer edge (4.1.E.1)

MOT #1	2016-01-08 10:00
MOT test number	663890724436
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

YR62PPX

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

See in this check if this HYUNDAI had different number plates.	
Mumber of plates	
Current registration	UK UK
Plate since	
Current registration	OK.
Fiele since	

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-20
Last registration	2024-02-29
Complete history	See info



Registration #1	2012-09-20	8 mi
Registration #2	2016-01-08	22.298 mi
Registration #3	2017-01-26	29.395 mi
Registration #4	2018-01-31	37.207 mi
Registration #5	2019-01-18	44.118 mi
Registration #6	2020-02-18	51.125 mi
Registration #7	2020-02-18	51.127 mi
Registration #8	2020-07-21	51.159 mi
Registration #9	2020-07-24	51.159 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		71.777 66
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number D4HABU508271