



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 S S40
Colour	Purple
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-10-03
Pictures	20
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-07
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	16
Total items failed	9

MOT #20	2023-09-08 11:08
MOT test number	952919252291
Result	✓ Passed
Next expiry date	2024-09-07

MOT #19	2022-09-15 13:34
MOT test number	685082098695
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #18	2021-09-30 07:52
MOT test number	719188663502
Result	✓ Passed

MOT #17	2020-10-08 07:52
MOT test number	639289532599
Result	✓ Passed

MOT #16	2020-10-08 07:52
MOT test number	856491612965
Result	✗ Failed
Pass with rectification	Nearside Rear Inner Position lamp not working (4.2.1 (a) (ii))

**MOT #15** 2019-10-03 15:21**MOT test number** 985011675367**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened All Discs Corroded (1.1.14 (a) (ii))**MOT #14** 2018-09-21 11:20**MOT test number** 551083915472**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2017-09-28 08:14**MOT test number** 448832501047**Result** ✓ Passed**MOT #12** 2016-10-10 15:12**MOT test number** 995307986466**Result** ✓ Passed**MOT #11** 2016-10-10 12:13**MOT test number** 589800542120**Result** ✗ Failed**Fail** Emissions not tested (7.3.A.1)**Fail** Brake performance not tested (3.7.A.1)

**MOT #10** 2016-02-04 09:39**MOT test number** 963876548255**Result** ✓ Passed**MOT #9** 2016-02-04 09:39**MOT test number** 330533337435**Result** ✗ Failed

**Pass with rectification** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' mirror toy (8.3.1b)

**MOT #8** 2015-02-17 12:57**MOT test number** 207308045010**Result** ✓ Passed**MOT #7** 2014-02-17 09:28**MOT test number** 389098144015**Result** ✓ Passed

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Offside Ball joint has slight play (2.2.B.1f)

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #6** 2013-02-18 15:59**MOT test number** 419439143011**Result** ✓ Passed

**MOT #5** 2013-02-18 13:52**MOT test number** 975899543098**Result** ✗ Failed**Fail** Front Brake lining(s) less than 1.5 mm thick (3.5.1g)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2012-02-25 10:08**MOT test number** 109226252456**Result** ✓ Passed**MOT #3** 2011-02-10 10:32**MOT test number** 835821141061**Result** ✓ Passed**MOT #2** 2010-02-17 16:09**MOT test number** 733058340036**Result** ✓ Passed**Notice** Front numberplate is damaged but readable at this time**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #12010-02-16 12:26

MOT test number414987140008

Result

Failed

- Notice

Front numberplate is damaged but readable at this time
- Fail

Nearside Side repeater missing (1.4.A.2b)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice

Engine coolant below minimum
- Fail

Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice

Offside rear tyre is perrished although not showing cords at this time



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
7 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	7 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 HX07TZZ
Plate since	2019-03-29
Current registration	 HX07TZZ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-01
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2007-03-01	17 mi
Registration #2	2010-02-16	26.009 mi
Registration #3	2010-02-17	26.083 mi
Registration #4	2011-02-10	32.820 mi
Registration #5	2012-02-25	40.573 mi
Registration #6	2013-02-18	46.670 mi
Registration #7	2013-02-18	46.670 mi
Registration #8	2014-02-17	53.438 mi
Registration #9	2015-02-17	60.444 mi
Registration #10	2016-02-04	63.777 mi
Registration #11	2016-02-04	63.777 mi
Registration #12	2016-02-04	63.777 mi
Registration #13	2016-02-04	63.777 mi
Registration #14	2016-02-04	63.777 mi
Registration #15	2016-02-04	63.777 mi
Registration #16	2016-02-04	63.777 mi
Registration #17	2016-02-04	63.777 mi
Registration #18	2016-02-04	63.777 mi
Registration #19	2016-02-04	63.777 mi
Registration #20	2016-02-04	63.777 mi
Registration #21	2016-02-04	63.777 mi
Registration #22	2016-02-04	63.777 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	70590