



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-12-24
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-19
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #15</b>	2022-01-31 14:52
<b>MOT test number</b>	754984196414
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-01-30
<b>Advice</b>	Front Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #14</b>	2020-11-14 11:35
<b>MOT test number</b>	435866383677
<b>Result</b>	✓ Passed
<b>Advice</b>	Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Offside Play in steering rack inner joint(s)
<b>Advice</b>	Gearbox mounting defective
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Rear Coil spring corroded x 2 (5.3.1 (b) (i))

<b>MOT #13</b>	2019-05-20 16:13
<b>MOT test number</b>	232766926560
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Play in steering rack inner joint(s)
<b>Advice</b>	Rear Coil spring corroded x2 (5.3.1 (b) (i))
<b>Advice</b>	Gearbox mounting defective

<b>MOT #12</b>	2018-05-21 10:28
<b>MOT test number</b>	671031269711
<b>Result</b>	✓ Passed

**MOT #11** 2017-05-10 15:31**MOT test number** 261939251325**Result** ✓ Passed**MOT #10** 2016-03-16 15:23**MOT test number** 398667995727**Result** ✓ Passed

- Advice** Brake pipes covered in grease
- Advice** Oil leak
- Advice** Nearside Rear tyre worn on outer edge
- Advice** Rear exhaust outer cover corroded
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)

**MOT #9** 2016-03-16 12:40**MOT test number** 233253503301**Result** ✗ Failed

- Advice** Brake pipes covered in grease
- Advice** Oil leak
- Fail** Rear fog lamp not working (1.3.2b)
- Advice** Front Exhaust has a minor leak of exhaust gases flexi (7.1.2)
- Advice** Nearside Rear tyre worn on outer edge
- Advice** Rear exhaust outer cover corroded
- Fail** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)

**MOT #8** 2015-03-18 10:25**MOT test number** 328867675059**Result** ✓ Passed**Notice** Nail in rear tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-03-12 13:41**MOT test number** 166451374483**Result** ✓ Passed**MOT #6** 2014-03-12 13:41**MOT test number** 636901674008**Result** ✗ Failed**Pass with rectification** Nearside Front Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Pass with rectification** Offside Front Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #5** 2013-03-19 11:46**MOT test number** 219128973062**Result** ✓ Passed**MOT #4** 2013-03-19 11:46**MOT test number** 679588173013**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2012-03-17 11:19**MOT test number** 325417072074**Result** ✓ Passed



MOT #2	2011-03-16 12:22
MOT test number	448385771067
Result	✓ Passed

MOT #1	2010-03-03 15:34
MOT test number	562822860003
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Nearside rear tyre has a screw in the tread



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-20
Last registration	2022-01-31
Complete history	<a href="#">See info</a>



Registration #1	2007-03-20	10 mi
Registration #2	2010-03-03	28.831 mi
Registration #3	2011-03-16	34.932 mi
Registration #4	2012-03-17	42.054 mi
Registration #5	2013-03-19	50.046 mi
Registration #6	2014-03-12	63.020 mi
Registration #7	2015-03-18	66.907 mi
Registration #8	2016-03-16	73.645 mi
Registration #9	2016-03-20	75.377 mi
Registration #10	2016-03-20	75.377 mi
Registration #11	2016-03-20	75.377 mi
Registration #12	2016-03-20	75.377 mi
Registration #13	2016-03-20	75.377 mi
Registration #14	2016-03-20	75.377 mi
Registration #15	2016-03-20	75.377 mi
Registration #16	2016-03-20	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4018117