





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	TIGUAN SE NAV TDI BMT
Colour	Grey
Year of manufacture	2018
Top speed	127 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

### Entry 3

Date 2023-03-09

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-08-06
------	------------

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1


Date 2021-08-05

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #5	2024-03-01 10:50
MOT test number	301906319105
Result	✓ Passed
Next expiry date	2025-03-01

MOT #4	2023-03-02 23:32
MOT test number	346727504091
Result	✓ Passed

MOT #3		2022-06-13 09:56
MOT test	number	847706278162
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2		2021-07-01 09:16
MOT test	number	187744369050
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge BOTH SIDES (5.2.3 (e))	
Advice	Rear Tyre slightly damaged/cracking or perishing BOTH SIDES (5.2.3 (d) (ii))	
Advice	Front Tyre slightly damaged/cracking or perishing BOTH SIDES (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2021-06-30 12:20 **MOT test number** 155606848089 Result × Failed Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Front Tyre slightly damaged/cracking or perishing BOTH SIDES (5.2.3 (d) (ii)) **Advice Advice** Front Tyre worn close to legal limit/worn on edge BOTH SIDES (5.2.3 (e)) Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) **Advice** Rear Tyre slightly damaged/cracking or perishing BOTH SIDES (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



CK18UZM report date: 2024-03-28

### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	1 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

### Damage 1


Date	
Category	
Туре	
Damage 2	

Damage 2

Date

Category

**Type** 



### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

CK18UZM

report date: 2024-03-28

# For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

### Plate changes

More info >

CarCheck.co.uk page 8/11



CK18UZM report date: 2024-03-28

### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-21
Last registration	2024-03-01
Complete history	See info



Registration #1	2018-06-21	11 mi
Registration #2	2021-06-30	34.202 mi
Registration #3	2021-07-01	34.202 mi
Registration #4		71.777 66
Registration #5		0.77 sc
Registration #6		71.777 es
Registration #7		D.777 66
Registration #8		71.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	see crash video



# Dimensions & weight

Width	2099 mm
Height	1632 mm
Length	4486 mm
Wheel base	2681 mm
Kerb weight	1568 kg
Max. allowed weight	2150 kg

# Additional information

Fuel tank capacity	58
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	DFGA845412