



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 S
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	140 g/km
CO2 label	E





MOT history

MOT expiry date	2024-09-03
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	65
Total items failed	9

MOT #19	2023-09-04 10:24
MOT test number	483492999500
Result	✓ Passed
Next expiry date	2024-09-03
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Rear Exhaust mounting defective (6.1.2 (a))

MOT #18	2023-09-04 09:14
MOT test number	609701253049
Result	✗ Failed
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
Advice	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #17**

2022-07-21 15:29

MOT test number

248094921795

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Edges are completely bald (5.2.3 (e))
- Advice** Rear exhaust bracket deteriorated

MOT #16

2022-07-21 13:53

MOT test number

563273490197

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Edges are completely bald (5.2.3 (e))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear exhaust bracket deteriorated
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #15

2021-06-22 10:22

MOT test number

180320404677

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2021-06-22 09:04

MOT test number

522368037466

Result**✗ Failed**

- MAJOR** Windscreen washer not working (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13

2020-06-23 09:12

MOT test number

426087196843

Result**✓ Passed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge On inner edge of tyre (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing In tyre tread (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge On inner edge of tyre (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing In tyre tread (5.2.3 (d) (ii))
- Advice** Rear Coil spring corroded Both rear springs (5.3.1 (b) (i))

**MOT #12**

2020-06-23 09:12

MOT test number

488185132480

Result**✗ Failed****Pass with rectification** Front Exhaust system insecure (6.1.2 (a))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Coil spring corroded Both rear springs (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On inner edge of tyre (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing In tyre tread (5.2.3 (d) (ii))**Pass with rectification** Rear Exhaust system insecure (6.1.2 (a))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge On inner edge of tyre (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing In tyre tread (5.2.3 (d) (ii))**MOT #11**

2019-06-27 13:11

MOT test number

464384833001

Result**✓ Passed****Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 185/65/15 (5.2.3 (d) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))

**MOT #10**

2019-06-25 12:38

MOT test number

657149970615

Result**✗ Failed**

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing 185/65/15 (5.2.3 (d) (ii))
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #9

2018-06-23 08:18

MOT test number

139025966638

Result**✓ Passed**

- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #8

2017-06-23 08:18

MOT test number

100267465137

Result**✓ Passed**

**MOT #7** 2017-06-23 08:18**MOT test number** 232061855949**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2016-06-18 09:08**MOT test number** 654285057220**Result** ✓ Passed**MOT #5** 2016-06-18 09:08**MOT test number** 394691672852**Result** ✗ Failed**Pass with rectification** Rear Exhaust system not adequately supported (7.1.1)**MOT #4** 2015-04-22 16:09**MOT test number** 865582915124**Result** ✓ Passed**Notice** Nearside front tyre wearing slightly on the outer edge**Notice** Nearside rear wheel bearing slightly noisy



MOT #3	2015-04-22 15:58
MOT test number	298282615148
Result	✗ Failed
Fail	Offside Front Headlamp not working on dipped beam (1.7.5a)
Notice	Nearside front tyre wearing slightly on the outer edge
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Rear Wheel stud(s) missing (4.2.A.1e)
Notice	Nearside rear wheel bearing slightly noisy
Fail	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #2	2013-12-31 10:39
MOT test number	617595863394
Result	✓ Passed

MOT #1	2012-11-07 09:52
MOT test number	328752212398
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
3 September 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	3 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-10-08
Last registration	2023-09-04
Complete history	See info



Registration #1	2009-10-08	21 mi
Registration #2	2012-11-07	38.506 mi
Registration #3	2013-12-31	42.581 mi
Registration #4	2015-04-22	46.682 mi
Registration #5	2015-04-22	46.682 mi
Registration #6	2016-06-18	52.622 mi
Registration #7	2016-06-18	52.622 mi
Registration #8	2017-06-23	57.240 mi
Registration #9	2017-06-23	57.240 mi
Registration #10	2018-06-23	59.675 mi
Registration #11	2019-06-23	62.110 mi
Registration #12	2020-06-23	64.545 mi
Registration #13	2021-06-23	66.980 mi
Registration #14	2022-06-23	69.415 mi
Registration #15	2023-06-23	71.850 mi
Registration #16	2024-06-23	74.285 mi
Registration #17	2025-06-23	76.720 mi
Registration #18	2026-06-23	79.155 mi
Registration #19	2027-06-23	81.590 mi
Registration #20	2028-06-23	84.025 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

FGAJ0529384