




report date: 2024-03-28

General information

Make	SUZUKI
Model	GRAND VITARA 16V
Colour	Grey
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	183 Nm at 4.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	208 g/km
CO2 label	K





MOT history

MOT expiry date	2021-09-25
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	22
Total items failed	1

MOT #10	2020-09-24 10:26
MOT test number	218797447928
Result	✓ Passed
Next expiry date	2021-09-25
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Fuel Pipe/s corroded

MOT #9	2019-09-16 15:43
MOT test number	727319596201
Result	✓ Passed

MOT #8	2018-09-13 11:38
MOT test number	493317883844
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



MOT #7 2017-09-26 09:31

MOT test number 441409425580

Result ✔ Passed

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Towball/hitch not fitted at time of test or electrics
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Brake pipes coated in underseal/grease
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #6 2017-09-26 09:31

MOT test number 343953015070

Result ✘ Failed

- Advice** Brake pipes coated in underseal/grease
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Towball/hitch not fitted at time of test or electrics
- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #5 2016-05-27 13:00

MOT test number 825687303367

Result ✔ Passed

- Advice** Car covered in mud underneath
- Advice** Offside Front inner of brake disc corroded



MOT #4	2015-05-05 17:23
MOT test number	719655025198
Result	✓ Passed
Notice	All Tyres Wearing On Edges
Notice	Under-trays fitted obscuring some underside components

MOT #3	2014-05-09 11:52
MOT test number	768019024120
Result	✓ Passed

MOT #2	2013-03-20 17:00
MOT test number	535289173023
Result	✓ Passed

MOT #1	2012-03-14 11:05
MOT test number	818494572088
Result	✓ Passed



Tax & MOT check

X
Untaxed

Tax expired:
15 January 2021

X
MOT

Expired:
25 September 2021

Tax status Expired at 15 January 2021

Days left 1199 days too late

MOT expiry date 25 September 2021

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	SL09PLU
Plate since	2024-03-28
Current registration	SL09PLU
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled. If not, and you buy this SUZUKI then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2009-04-18
Last registration	2020-09-24
Complete history	See info



Registration #1	2009-04-18	19 mi
Registration #2	2012-03-14	27.224 mi
Registration #3	2013-03-20	36.153 mi
Registration #4	2014-05-09	44.584 mi
Registration #5	2015-05-05	57.370 mi
Registration #6	2016-05-27	71.311 mi
Registration #7	2019-09-24	85.252 mi
Registration #8	2019-09-24	85.252 mi
Registration #9	2019-09-24	85.252 mi
Registration #10	2019-09-24	85.252 mi
Registration #11	2019-09-24	85.252 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1695 mm
Length	4470 mm
Wheel base	2640 mm
Kerb weight	1595 kg
Max. allowed weight	2070 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	J20A-416114