





General information

Make	HONDA
Model	INSIGHT IMA EX
Colour	Black
Year of manufacture	2011
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	1 speed CVT


Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	60.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	61.4 mpg
CO2 emission	105 g/km
CO2 label	В





Internet history	
Entry 1	
Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-11
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	11
Total items failed	2

MOT #13	2024-02-29 08:13
MOT test number	102636841180
Result	✓ Passed
Next expiry date	2025-03-11
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12		2023-02-24 08:19
MOT test	number	554385915737
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2022-03-02 12:50
MOT test number	422808388926
Result	✓ Passed

MOT #10	2021-03-12 09:46
MOT test number	262183594998
Result	✓ Passed





MOT #9		2021-03-10 17:09
MOT test	number	380490813598
Result		🗙 Failed
MAJOR	Service brake efficiency below requirements (1.2.2 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
MAJOR	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
DANGER	OUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR	Tarking brake enciency below requirements (1.4.2 (d) (i))	
MAJOR	Nearside Rear Brake disc significantly and obviously worn $(1.1.14$ (a) (i))	

MOT #8	2019-07-09 09:23
MOT test number	428218159073
Result	✓ Passed

MOT #7		2019-07-09 09:23
MOT test number		363929100865
Result		🗙 Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))	

МОТ #6	2018-07-11 11:48
MOT test number	843405799935
Result	✓ Passed

MOT #5	2017-07-11 14:32
MOT test number	173715728791
Result	✓ Passed





MOT #4	2016-06-24 10:39	
MOT test number	426595184048	
Result	✓ Passed	
MOT #3	2016-06-23 16:02	
MOT test number	815070806205	
Result	🗙 Failed	
Advice Front Brake pad(s) wearing thin (3.5.1g)		
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)		
Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		

MOT #2	2015-07-07 11:51
MOT test number	697248485188
Result	✓ Passed

MOT #1	2014-07-18 10:52
MOT test number	355949294107
Result	✓ Passed



Tax & MOT check

Tax due: 1 March 2025	✓ Taxed	Expires: 11 March 2025	✓ МОТ
Tax status			Valid until 1 March
Days left			306
MOT expiry date			11 March 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		59	

Vehicle class	59
Band	В
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K K
Damage 2	AMPL
	F Store
Date	 1. F
Category	 ant
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-07-21
Last registration	2024-02-29
Complete history	<u>See info</u>



Registration #1	2011-07-21	23 mi
Registration #2	2014-07-18	24.108 mi
Registration #3	2015-07-07	34.639 mi
Registration #4	2016-06-23	48.137 mi
Registration #5	2016-06-24	48.137 mi
Registration #6	2017-07-11	60.481 mi
Registration #7	2018-07-11	71.837 mi
Registration #8	2019-07-09	84.720 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 esi

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight	
Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 2012079