





### General information

Make	BMW	
Model	318 118I M SPORT SHADOW EDITION	
Colour	White	
Year of manufacture	2018	
Top speed	130 mph	
Gearbox	6 speed Manual	

# Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 1.250 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





## Internet history

Entry 1

Date Pictures 2022-06-24

40

Listing price

View report



source: cargurus.co.uk



# MOT history

MOT expiry date	2024-05-04
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	24
Total items failed	0

MOT #6	2023-05-05 15:35
MOT test number	164505797763
Result	✓ Passed
<b>Next expiry date</b> 2024-05-04	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5		2023-05-04 13:30
MOT test r	umber	302829840828
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>MAJOR</b> Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tread (5.2.3 (d) (i))		
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #4		2022-05-03 15:59
MOT test	number	569422277677
Result		✓ Passed
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Nail in tyre	



MOT #3	2022-03-10 12:41	
MOT test number	247778759862	
Result	✓ Passed	
Advice Coolant Level Low		
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front arm inner bush (5.3.4 (a) (i))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Items removed from driver's view prior to test		
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front arm inner bush (5.3.4 (a) (i))		
Advice Front Brake pad(s) wearing thin Both Sides (1.1.13 (a) (ii))		

MOT #2	2022-03-10 12:15
MOT test number	558277934547
Result	🗙 Failed
MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperat	tive (5.2.3 (h))
Advice Items removed from driver's view prior to test	
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in exe arm inner bush (5.3.4 (a) (i))	cessive movement Front
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Coolant Level Low	
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in e arm inner bush (5.3.4 (a) (i))	excessive movement Front
Advice Front Brake pad(s) wearing thin Both Sides (1.1.13 (a) (ii))	





MOT #1		2021-04-06 09:35
MOT test	number	978077097299
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin nearside and offside inner pads (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))	



Tax & MOT check

Taxed Tax due: 1 August 2024	MOT Expires: 4 May 2024
Tax status	Valid until 1 August
Days left	95
MOT expiry date	4 May 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Anne
Туре	K K
Damage 2	AMPLE
Damage 2	e et - I - I
Date	S.
Category	AMPT
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	
*************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plate	5.
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



FL18WPU report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-10
Last registration	2023-05-05
Complete history	See info



Registration #1	2018-05-10	8 mi
Registration #2	2021-04-06	33.159 mi
Registration #3	2022-03-10	49.202 mi
Registration #4	2022-03-10	49.202 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.317 esi





### Car features

S0225	Air conditioning
\$0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	91%
Children	83%
Pedestrian	63%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	1765 mm
Height	1421 mm
Length	4329 mm
Wheel base	2690 mm
Kerb weight	1305 kg
Max. allowed weight	1870 kg
Additional information	
Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	30375322