



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 2 PICASSO
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	135 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-26
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #23	2022-03-23 14:02
MOT test number	460011709183
Result	✓ Passed
Next expiry date	2023-03-22

MOT #22	2022-03-22 19:05
MOT test number	937983382631
Result	✗ Failed

MAJOR Headlamp aim projected beam image is obviously incorrect both sides (4.1.2 (c))

MAJOR Front Exhaust system insecure (6.1.2 (a))

MOT #21	2021-05-04 14:07
MOT test number	103891403643
Result	✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2021-04-20 14:05
MOT test number	201072820923
Result	✗ Failed

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

MAJOR Brakes imbalanced across an axle or low (1.2.1 (b) (i))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

**MOT #19** 2020-04-23 13:32**MOT test number** 407689309583**Result** ✓ Passed**MOT #18** 2019-04-26 14:02**MOT test number** 989944608148**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #17** 2019-04-23 11:16**MOT test number** 471873625094**Result** ✗ Failed**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Emissions not tested cooling fan fault (8.2.2.2 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2018-04-21 08:57**MOT test number** 413698466421**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front coil spring corroded (2.4.C.1b)

**MOT #15** 2017-04-22 09:49**MOT test number** 167293819147**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)**MOT #14** 2016-04-09 09:16**MOT test number** 608224187459**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #13** 2015-04-18 11:23**MOT test number** 779368305196**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2014-04-03 11:34**MOT test number** 567783394037**Result** ✓ Passed**MOT #11** 2013-04-29 14:32**MOT test number** 845279713170**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2013-04-22 10:49**MOT test number** 986132713116**Result** ✗ Failed**Fail** Power steering pipe(s) or hose(s) leaking (2.3.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2012-04-23 11:51**MOT test number** 259224312419**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8** 2011-04-18 11:31**MOT test number** 526748701103**Result** ✓ Passed**Notice** Rear axle has slight corrosion**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #7** 2010-04-27 14:30**MOT test number** 831617710178**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

**MOT #6**

2010-04-26 12:43

MOT test number

730656510151

Result

✗ Failed

Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Rear Exhaust mounting missing (7.1.1b)**MOT #5**

2009-07-31 14:16

MOT test number

852872019208

Result

✓ Passed

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nail in offside rear tyre**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4**

2008-08-05 11:06

MOT test number

714058118227

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3**

2007-06-07 11:58

MOT test number

761418257113

Result

✓ Passed



MOT #2	2007-04-26 14:28
MOT test number	200326317422
Result	✓ Passed

MOT #1	2007-04-24 17:06
MOT test number	330814917129
Result	✗ Failed

- Fail

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Offside Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-04-17
Last registration	2022-03-23
Complete history	See info



Registration #1	2004-04-17	14 mi
Registration #2	2007-04-24	27.809 mi
Registration #3	2007-04-26	27.809 mi
Registration #4	2007-06-07	27.972 mi
Registration #5	2008-08-05	36.914 mi
Registration #6	2009-07-31	44.342 mi
Registration #7	2010-04-26	51.191 mi
Registration #8	2010-04-27	51.191 mi
Registration #9	2011-04-18	53.574 mi
Registration #10	2012-04-23	57.244 mi
Registration #11	2013-04-22	59.531 mi
Registration #12	2013-04-29	59.540 mi
Registration #13	2014-04-03	62.923 mi
Registration #14	2015-04-03	65.306 mi
Registration #15	2016-04-03	67.689 mi
Registration #16	2017-04-03	70.072 mi
Registration #17	2018-04-03	72.455 mi
Registration #18	2019-04-03	74.838 mi
Registration #19	2020-04-03	77.221 mi
Registration #20	2021-04-03	79.604 mi
Registration #21	2022-04-03	81.987 mi
Registration #22	2023-04-03	84.370 mi
Registration #23	2024-04-03	86.753 mi
Registration #24	2025-04-03	89.136 mi
Registration #25	2026-04-03	91.519 mi



Safety ratings

NCAP rating



Video

[see crash video](#)

Dimensions & weight

Width

1751 mm

Height

1637 mm

Length

4276 mm

Wheel base

2760 mm

Kerb weight

1240 kg

Additional information

Fuel tank capacity

55 l

Fuel delivery

Multi-Point Injection

Number of doors

5

Engine number

FX4T2143295