



report date: 2024-03-28

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Green
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-06-26
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-10-27
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	51
Total items failed	4

## MOT #19 2023-10-05 13:37

MOT test number 590953241266

Result ✓ Passed

Next expiry date 2024-10-27

**Advice** Nearside Rear Parking brake lever defective but can be satisfactorily operated not returning fully in off position (1.1.6 (d))

**Minor** Offside Rear Brake hose slightly chafed (1.1.12 (b) (i))

**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Rear Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

## MOT #18 2022-10-25 14:32

MOT test number 538854207044

Result ✓ Passed

**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2021-10-28 11:22

**MOT test number**

314449872259

**Result**

✓ Passed

**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #16**

2020-10-23 14:04

**MOT test number**

723357665152

**Result**

✓ Passed

**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))**MOT #15**

2019-04-20 12:47

**MOT test number**

621352539648

**Result**

✓ Passed

**MOT #14**

2018-06-28 14:01

**MOT test number**

702261386672

**Result**

✓ Passed

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner (5.3.4 (a) (i))**Advice** Nearside Rear Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13** 2017-07-04 14:53**MOT test number** 233645263525**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2016-05-06 11:59**MOT test number** 832040361401**Result** ✓ Passed**MOT #11** 2016-05-06 11:59**MOT test number** 625798371473**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #10** 2015-05-08 12:54**MOT test number** 845068925197**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**MOT #9** 2015-05-08 12:54**MOT test number** 697958225159**Result** ✗ Failed**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

**MOT #8** 2014-05-16 11:39**MOT test number** 508346334190**Result** ✓ Passed**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #7** 2013-05-17 12:30**MOT test number** 247847933414**Result** ✓ Passed**MOT #6** 2013-05-13 15:15**MOT test number** 346073033128**Result** ✗ Failed**Notice** Offside headlamp retaining bracket broken**Fail** Nearside Headlamp insecure (1.7.3)**MOT #5** 2012-05-04 12:45**MOT test number** 716015722139**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #4** 2011-05-11 16:09**MOT test number** 265341331167**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)**Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)



MOT #3

2010-05-13 17:01

MOT test number

300373030160

Result

✓ Passed

- Advice

Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice

Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice

Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice

Child seat fitted not allowing full inspection of adult belt
- Advice

Nearside Rear Shock absorber has a slightly worn bush (2.7.4)

**MOT #2**

2010-05-13 14:30

**MOT test number**

582083030188

**Result****✗ Failed**

- Advice** Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Fail** Rear registration plate deteriorated (6.3.1d)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #1**

2009-03-16 12:26

**MOT test number**

774725479015

**Result****✓ Passed**

- Notice** Rear # plate delaminating - legible at present
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)





Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-22
Last registration	2023-10-05
Complete history	<a href="#">See info</a>



Registration #1	2006-03-22	15 mi
Registration #2	2009-03-16	50.062 mi
Registration #3	2010-05-13	65.863 mi
Registration #4	2010-05-13	65.864 mi
Registration #5	2011-05-11	80.602 mi
Registration #6	2012-05-04	97.564 mi
Registration #7	2013-05-13	111.251 mi
Registration #8	2013-05-17	111.267 mi
Registration #9	2014-05-16	126.843 mi
Registration #10	2015-05-08	140.240 mi
Registration #11	2016-05-08	153.277 mi
Registration #12	2017-05-08	166.314 mi
Registration #13	2018-05-08	179.351 mi
Registration #14	2019-05-08	192.388 mi
Registration #15	2020-05-08	205.425 mi
Registration #16	2021-05-08	218.462 mi
Registration #17	2022-05-08	231.499 mi
Registration #18	2023-05-08	244.536 mi
Registration #19	2023-10-05	257.573 mi
Registration #20	2024-03-28	270.610 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G