





report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 SW SPORT
Colour	Blue
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date	2021-05-20
Pictures	0
Listing price	View report

source: autotrader.co.uk

Entry 1

y -		
Date	2021-02-03	
Pictures	9	
Listing price	View report	









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-04	
MOT pass rate	81 %	
MOT passed	13	
Failed MOT tests	3	
Total advice items	7	
Total items failed	12	

MOT #16	2024-04-05 09:28
MOT test number	445680662955
Result	✓ Passed
Next expiry date	2025-04-04
Advice Rear Tyre slightly damaged/cracking or perishing BOTH SIDES (5.2.3 (d) (ii))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Front Suspension arm pin or bush worn but not resulting in excessive moveme (5.3.4 (a) (i))	nt BOTH SIDES

MOT #15	2023-03-23 16:01
MOT test number	760166426332
Result	✓ Passed

CarCheck.co.uk page 3/13



LS09RYV

report date: 2024-03-29

MOT #14	2023-03-08 16:30
MOT test number	792595326905
Result	× Failed
Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Advice Front Registration plate insecure but not likely to fall off (0.1 (a))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail Oil leaking excessively from engine (8.4.1 (a) (i))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))	

MOT #13	2022-04-05 13:27
MOT test number	657670479737
Result	✓ Passed
MOT #12	2021-05-14 09:26
MOT test number	895548234868
Result	✓ Passed
MOT #11	2020-06-06 14:53
MOT test number	247281254287
Result	✓ Passed
Advice Nearside front tyre wearing low on the inner edge	

MOT #10	2019-04-15 09:25
MOT test number	124972815483
Result	✓ Passed

CarCheck.co.uk page 4/13



LS09RYV

report date: 2024-03-29

MOT #9	2018-04-19 14:36
MOT test number	784272488752
Result	✓ Passed
MOT #8	2018-04-18 15:22
MOT test number	541305918594
Result	★ Failed
Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Fail Nearside Rear Stop lamp not working (1.2.1b)	
MOT #7	2017-04-11 09:08
MOT test number	738201905621

MOT #7	2017-04-11 09:08
MOT test number	738201905621
Result	✓ Passed
MOT #6	2016-03-30 09:10
MOT test number	772177564464
Result	✓ Passed
MOT #5	2016-03-30 09:10
MOT test number	612125698242
Result	≍ Failed
Pass with rectification Stop lamp not working Offside (1.2.1b)	

CarCheck.co.uk page 5/13



Result

LS09RYV report date: 2024-03-29

✓ Passed

MOT #4	2015-04-16 10:16
MOT test number	827706405104
Result	✓ Passed
MOT #3	2014-04-14 10:08
MOT test number	576464804183
Result	✓ Passed
MOT #2	2013-03-26 12:07
MOT test number	229155883041
Result	✓ Passed
MOT #1	2012-04-17 14:00
MOT test number	118898002108

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

LS09RYV

report date: 2024-03-29

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 10/13



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13



LS09RYV

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-05-19
Last registration	2024-04-05
Complete history	See info



Registration #1	2009-05-19	25 mi
Registration #2	2012-04-17	2.930 mi
Registration #3	2013-03-26	3.461 mi
Registration #4	2014-04-14	9.988 mi
Registration #5	2015-04-16	17.060 mi
Registration #6	2016-03-30	23.885 mi
Registration #7	2016-03-30	23.885 mi
Registration #8	2017-04-11	31.310 mi
Registration #9	2018-04-18	39.503 mi
Registration #10	2018-04-19	39.507 mi
Registration #11		71.777 es
Registration #12		11.777 es
Registration #12 Registration #13		11.777 es
-		11.777 ea 11.777 ea
Registration #13		11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14 Registration #15		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #13 Registration #14 Registration #15 Registration #16		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4156 mm
Wheel base	2540 mm
Kerb weight	1328 kg
Max. allowed weight	1737 kg

Additional information

Fuel tank capacity	50
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number FHBD0645851