



report date: 2024-03-28

General information

Make	AUDI
Model	A6 TDI
Colour	Silver
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	160 g/km
CO2 label	G





MOT history

MOT expiry date	2023-05-25
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	31
Total items failed	14

MOT #17 2022-05-26 09:24

MOT test number 445603474421

Result ✓ Passed

Next expiry date 2023-05-25

Advice Nearside Rear Tyre worn close to legal limit/worn on edge close to limits (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge close to limits (5.2.3 (e))

Advice Full underbody inspection NOT fully carried out due to under trays fitted

MOT #16 2022-05-26 09:24

MOT test number 589411925859

Result ✗ Failed

Advice Full underbody inspection NOT fully carried out due to under trays fitted

Advice Offside Rear Tyre worn close to legal limit/worn on edge close to limits (5.2.3 (e))

Pass with rectification Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge close to limits (5.2.3 (e))

Pass with rectification Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #15**

2021-05-05 13:46

MOT test number

119235985634

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Eml on**Advice** Offside Rear seat belt slow to retract**MOT #14**

2021-05-04 10:53

MOT test number

229856062822

Result

✗ Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Eml on**Fail** Central Seat belt not functioning as intended (7.1.2 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Rear seat belt slow to retract**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #13** 2020-05-13 10:54**MOT test number** 909252657425**Result** ✓ Passed**MOT #12** 2019-03-20 19:01**MOT test number** 439586221844**Result** ✓ Passed**Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2017-12-12 13:55**MOT test number** 909939661493**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2017-01-04 15:12**MOT test number** 492505598111**Result** ✓ Passed**MOT #9** 2017-01-04 13:53**MOT test number** 790039452896**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8** 2015-12-18 16:13**MOT test number** 657237896434**Result** ✓ Passed**MOT #7** 2014-06-03 11:21**MOT test number** 868844854148**Result** ✓ Passed**MOT #6** 2013-05-08 15:40**MOT test number** 839548023176**Result** ✓ Passed**MOT #5** 2013-03-27 11:41**MOT test number** 958796583071**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #4** 2012-07-03 11:27**MOT test number** 285835582444**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2011-10-03 11:54**MOT test number** 655946571275**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nail in nearside front tyre**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-07-02 09:29**MOT test number** 528483681179**Result** ✓ Passed**Advice** Nearside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2010-03-10 15:02**MOT test number** 103349660060**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** NSF tyre has slight wall damage but not effecting structure of tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
31 May 2023

✕
MOT

Expired:
25 May 2023

Tax status	Expired at 31 May 2023
Days left	333 days too late
MOT expiry date	25 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-05
Last registration	2022-05-26
Complete history	See info



Registration #1	2007-03-05	14 mi
Registration #2	2010-03-10	26.640 mi
Registration #3	2011-07-02	31.701 mi
Registration #4	2011-10-03	32.308 mi
Registration #5	2012-07-03	40.259 mi
Registration #6	2013-03-27	51.498 mi
Registration #7	2013-05-08	51.498 mi
Registration #8	2014-06-03	65.522 mi
Registration #9	2015-12-18	84.590 mi
Registration #10	2016-05-20	95.377 mi
Registration #11	2016-05-20	95.377 mi
Registration #12	2016-05-20	95.377 mi
Registration #13	2016-05-20	95.377 mi
Registration #14	2016-05-20	95.377 mi
Registration #15	2016-05-20	95.377 mi
Registration #16	2016-05-20	95.377 mi
Registration #17	2016-05-20	95.377 mi
Registration #18	2016-05-20	95.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1459 mm
Length	4916 mm
Wheel base	2843 mm
Kerb weight	1540 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	BRE 108583