





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5 STR
Colour	Silver
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-07-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

(a) (i))

MOT #21 2021-12-08 10:06

MOT test number 503901654719

Result X Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material 2 Pipes on nearside rear (1.1.11 (c))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Slight corossion around rear suspension

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20 2020-10-27 10:39

MOT test number 476183645222

Result \(\sqrt{Passed} \)

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4

MOT #19 2019-04-29 13:20

MOT test number 823375652241

Result / Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

Minor Offside Registration plate lamp insecure (4.7.1 (c) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #18 2019-04-29 13:20

MOT test number 353943276442

Result X Failed

Advice Suspension arm pin or bush worn but not resulting in excessive movement both front (5.3.4 (a) (i))

Minor Offside Registration plate lamp insecure (4.7.1 (c) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #17 2018-04-26 12:52

MOT test number 295703999072

Result \square Passed

Advice Oil leak

Advice Nearside Rear coil spring corroded (2.4.C.1b)

Advice Under tray fitted

MOT #16 2018-04-26 09:25

MOT test number 478291771431

Result × Failed

Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)

Advice Oil leak

Fail Bootlid cannot be secured in the closed position (6.4.1)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Under tray fitted

Fail Offside Stop lamp not working (1.2.1b)

Advice Nearside Rear coil spring corroded (2.4.C.1b)

CarCheck.co.uk page 4/14



MOT #15 2017-04-29 13:50

MOT test number 257238244331

Result ✓ Passed

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Advice Under tray fitted

Advice O/S front wing damage

MOT #14 2017-04-28 15:21

MOT test number 250908779333

Result X Failed

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice O/S front wing damage

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Shock absorber has a serious fluid leak (2.7.3)

Advice Under tray fitted

MOT #13 2015-08-05 08:18

MOT test number 308219012169

Result ✓ Passed

MOT #12 2015-08-05 08:18

MOT test number 198936594440

Result X Failed

Pass with rectification Offside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #11

MOT test number

456232104225

Result

Notice Engine covers fitted obscuring some components in the engine bay

MOT test number
957321694103

Result

Notice Engine covers fitted obscuring some components in the engine bay

Fail Offside Front coil spring broken (2.4.C.1a)

Notice NEARSIDE FRONT TYRE INNER EDGE WORN

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #9

MOT test number

485920313223

Result

Notice Oil leak

2013-07-29 17:18

√ Passed

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #7 2012-07-24 13:30 **MOT** test number 135306102285 Result × Failed **Notice** Under-trays fitted obscuring some underside components Fail Parking brake: efficiency below requirements (3.7.B.7) Notice Child seat fitted not allowing full inspection of adult belt Notice N/s/r and o/s/r shocker dust covers loose Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #6
 2011-08-01 13:40

 MOT test number
 975843611255

 Result
 ✓ Passed

 Notice
 Rear pads?

MOT #5

MOT test number

810594680137

Result

✓ Passed

MOT #4

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.2b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.2b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.2b)

CarCheck.co.uk page 7/14



MOT #3 2009-07-03 14:33

MOT test number 491454589140

Result X Failed

Fail Horn not working (1.6.2a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.2b)

Fail Centre Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.2b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.2b)

MOT #2 2008-07-12 15:09

MOT test number 452074698104

Result ✓ Passed

MOT #1 2007-07-31 09:41

MOT test number 530232117200

Result
✓ Passed

CarCheck.co.uk page 8/14




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How m VOLKSWAGEN have? Check it in the premium report and see all owner registrations.	

CarCheck.co.uk page 11/14



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-05-11
Last registration	2021-12-08
Complete history	See info



Registration #1	2004-05-11	8 mi
Registration #2	2007-07-31	75.004 mi
Registration #3	2008-07-12	87.385 mi
Registration #4	2009-07-03	88.400 mi
Registration #5	2009-07-10	88.400 mi
Registration #6	2010-07-03	92.382 mi
Registration #7	2011-08-01	104.099 mi
Registration #8	2012-07-24	118.195 mi
Registration #9	2012-07-25	118.199 mi
Registration #10	2013-07-29	135.116 mi
Registration #11	2014-07-10	144.818 mi
Registration #12	2014-07-21	145.034 mi
Registration #13		11.107-00
Registration #13 Registration #14		1.77 m
		1.77 m
Registration #14		1.77 m
Registration #14 Registration #15		1.77 m
Registration #14 Registration #15 Registration #16		11.77 es 11.77 es 11.77 es 11.77 es
Registration #14 Registration #15 Registration #16 Registration #17		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11.77 es 11.77 es 11.77 es 11.77 es 11.77 es 11.77 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es 11,777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
0 0 1	7.47.4

CarCheck.co.uk page 14/14

Number of seats	5
Engine number	AVQ 050944