



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT DESIGN
Colour	Black
Year of manufacture	-
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	175 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-07
Pictures	25
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #17</b>	2023-08-02 10:15
<b>MOT test number</b>	926202543539
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-08-05

<b>MOT #16</b>	2022-08-06 14:11
<b>MOT test number</b>	440299195142
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Minor</b>	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Minor</b>	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

<b>MOT #15</b>	2022-08-06 08:42
<b>MOT test number</b>	190868769226
<b>Result</b>	✗ Failed
<b>Minor</b>	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
<b>Fail</b>	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Minor</b>	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
<b>Minor</b>	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

<b>MOT #14</b>	2021-07-20 13:35
<b>MOT test number</b>	464104544556
<b>Result</b>	✓ Passed



<b>MOT #13</b>	2021-07-20 10:07
<b>MOT test number</b>	353634936459
<b>Result</b>	✗ Failed
<b>Fail</b>	Brake pipe excessively corroded Both Front to Rear Pipes (1.1.11 (c))

<b>MOT #12</b>	2020-07-21 09:28
<b>MOT test number</b>	699493221331
<b>Result</b>	✓ Passed
<b>Advice</b>	Brake pipe corroded, covered in grease or other material both front to rears (1.1.11 (c))
<b>Advice</b>	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b>	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
<b>Advice</b>	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

<b>MOT #11</b>	2019-04-05 15:53
<b>MOT test number</b>	827059411436
<b>Result</b>	✓ Passed
<b>Advice</b>	Brake pipe corroded, covered in grease or other material Both Front to Rear Slightly Corroded (1.1.11 (c))

<b>MOT #10</b>	2019-04-05 08:37
<b>MOT test number</b>	651871330929
<b>Result</b>	✗ Failed
<b>Advice</b>	Brake pipe corroded, covered in grease or other material Both Front to Rear Slightly Corroded (1.1.11 (c))
<b>Fail</b>	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #9** 2018-04-10 11:52**MOT test number** 853166563270**Result** ✓ Passed**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**MOT #8** 2018-04-10 08:04**MOT test number** 456892554837**Result** ✗ Failed**Advice** Offside Brake pipe slightly corroded front to rear (3.6.B.2c)**Fail** Nearside Rear Brake pipe excessively corroded across floor (3.6.B.2c)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #7** 2017-04-11 07:28**MOT test number** 362958460845**Result** ✓ Passed**MOT #6** 2016-03-23 17:04**MOT test number** 830772086056**Result** ✓ Passed**MOT #5** 2015-03-26 17:32**MOT test number** 675615685083**Result** ✓ Passed**MOT #4** 2014-03-20 16:26**MOT test number** 588339374060**Result** ✓ Passed



MOT #3	2013-04-15 13:20
MOT test number	617055803124
Result	✓ Passed

MOT #2	2013-04-12 13:17
MOT test number	719452903138
Result	✗ Failed
<div><div>Fail</div>Offside Rear coil spring incomplete (2.4.C.1a)</div> <div><div>Notice</div>Child seat fitted not allowing full inspection of adult belt</div>	

MOT #1	2012-04-07 11:20
MOT test number	796278692080
Result	✓ Passed



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>LN09OKG</b>
Plate since	2019-03-29
Current registration	<b>LN09OKG</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-05-27
Last registration	2023-08-02
Complete history	<a href="#">See info</a>



Registration #1	2009-05-27	9 mi
Registration #2	2012-04-07	11.059 mi
Registration #3	2013-04-12	17.392 mi
Registration #4	2013-04-15	17.434 mi
Registration #5	2014-03-20	27.417 mi
Registration #6	2015-03-26	41.386 mi
Registration #7	2016-03-23	55.992 mi
Registration #8	2017-04-11	61.423 mi
Registration #9	2018-04-10	63.873 mi
Registration #10	2018-04-10	63.873 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	20MP7099