




report date: 2024-03-28

General information

Make	SMART
Model	FORTWO COUPE PASSION MHD
Colour	Grey
Year of manufacture	2010
Top speed	90 mph
0 - 100 km/h	13.7 seconds
0 - 60 mph	13.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 2.800 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	61.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	65.7 mpg
CO2 emission	98 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-09-14
Pictures	6
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-19
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	12
Total items failed	10

MOT #17	2023-11-03 12:52
MOT test number	711954209251
Result	✓ Passed
Next expiry date	2024-11-19

MOT #16	2022-11-10 16:20
MOT test number	520631657331
Result	✓ Passed

MOT #15	2022-11-10 16:20
MOT test number	395563887709
Result	✗ Failed
<b>Pass with rectification</b> Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #14	2021-11-10 16:05
MOT test number	666768682320
Result	✓ Passed

**MOT #13** 2020-11-13 11:21**MOT test number** 174040352093**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #12** 2020-11-11 15:39**MOT test number** 652540773359**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2019-11-20 16:09**MOT test number** 338550884873**Result** ✓ Passed**MOT #10** 2018-10-15 09:36**MOT test number** 677040871648**Result** ✓ Passed**Advice** Offside Rear Wheel has restricted free movement adversely affecting wheel bearing check**MOT #9** 2017-11-10 16:29**MOT test number** 529574971164**Result** ✓ Passed**Advice** Both rear tyres perishing slightly**Advice** Offside front tyre perished slightly

**MOT #8** 2017-11-08 10:36**MOT test number** 642879449306**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Advice** Offside front tyre perished slightly**Fail** Offside Front Lower Suspension arm has excessive play in a pin/bush wishbone rear bush (2.4.G.2)**Advice** Both rear tyres perishing slightly**MOT #7** 2016-10-19 13:30**MOT test number** 442719051825**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #6** 2016-10-19 13:30**MOT test number** 382315046008**Result** ✗ Failed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #5** 2016-06-01 15:00**MOT test number** 298435057010**Result** ✓ Passed

**MOT #4** 2016-06-01 11:38**MOT test number** 857659729060**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #3** 2014-11-21 10:52**MOT test number** 425095324332**Result** ✓ Passed**MOT #2** 2014-10-28 12:25**MOT test number** 246811504386**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** O/s/f tyre on 3mm**MOT #1** 2013-08-05 13:01**MOT test number** 657587913216**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
19 November 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	19 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	KM60AXX
Plate since	2019-09-28
Current registration	KM60AXX
Plate since	2019-09-28

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-12-29
Last registration	2023-11-03
Complete history	<a href="#">See info</a>



Registration #1	2010-12-29	7 mi
Registration #2	2013-08-05	14.463 mi
Registration #3	2014-10-28	31.284 mi
Registration #4	2014-11-21	32.389 mi
Registration #5	2016-06-01	40.959 mi
Registration #6	2016-06-01	40.959 mi
Registration #7	2016-10-19	41.842 mi
Registration #8	2016-10-19	41.842 mi
Registration #9	2017-11-08	43.622 mi
Registration #10	2017-11-10	43.624 mi
Registration #11	2019-05-29	55.377 mi
Registration #12	2019-05-29	55.377 mi
Registration #13	2019-05-29	55.377 mi
Registration #14	2019-05-29	55.377 mi
Registration #15	2019-05-29	55.377 mi
Registration #16	2019-05-29	55.377 mi
Registration #17	2019-05-29	55.377 mi
Registration #18	2019-05-29	55.377 mi
Registration #19	2019-05-29	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	99 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21CM3838