





report date: 2024-03-29

General information

Make	FIAT
Model	500C ACTIVE
Colour	White
Year of manufacture	2012
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history


Entry 3

Date 2023-02-02


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-10-14
------	------------

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-08-14

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-02-17
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #13	2024-01-26 16:09
MOT test number	810741485219
Result	✓ Passed
Next expiry date	2025-02-17
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-02-18 10:16
MOT test number	918156993261
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11		2023-02-02 12:38
MOT test	number	763975908460
Result		× Failed
Advice	Both front brake discs have surface corrosion on inner side	
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Coil spring corroded both rear (5.3.1 (b) (i))	
Advice	Exhaust flexi deteriorated	
MAJOR	Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Nearside Front daytime running light not working	

2022-01-04 13:06	
470481672069	
✓ Passed	
2021-07-30 10:27	
985334896614	
✓ Passed	
2020-08-26 15:31	
608031435226	
✓ Passed	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7 2020-08-26 11:01

MOT test number 782558485457

Result X Failed

MAJOR Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2019-08-23 09:22

MOT test number 358395093166

Result ✓ Passed

Advice Both rear tyres have age related cracks

MOT #5 2018-08-22 10:31

MOT test number 651096239023

Result \(\sqrt{Passed} \)

MOT #4 2017-08-07 09:43

MOT test number 358541667045

Result \(\sqrt{Passed} \)

Advice Both rear tyres cracking in tread area

MOT #3 2016-08-15 11:16

MOT test number 475442491925

Result ✓ Passed

MOT #2 2015-08-10 11:24

MOT test number 879302925210

Result
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2015-08-10 11:24

MOT test number 788382625221

Result X Failed

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Pass with rectification Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	17 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



AY62ZBT report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



AY62ZBT report date: 2024-03-29

Owner history

e union mestery		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		e?
THE PARTY OF THE P		

THE STREET STREE		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK ME	
Plate since		
Current registration	OK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



AY62ZBT report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-01
Last registration	2024-01-26
Complete history	See info



Registration #1	2012-09-01	29 mi
Registration #2	2015-08-10	19.603 mi
Registration #3	2016-08-15	21.457 mi
Registration #4	2017-08-07	23.809 mi
Registration #5	2018-08-22	25.891 mi
Registration #6	2019-08-23	28.545 mi
Registration #7	2020-08-26	30.078 mi
Registration #8	2020-08-26	30.078 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/1

Number of axles 2

Engine number 6492127