






report date: 2024-03-28

## General information

Make	HONDA
Model	S2000 16V
Colour	Black
Year of manufacture	2000
Top speed	150 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	236 BHP
Max. torque	204 Nm at 7.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	28.3 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 2

Date 2022-01-16

Pictures 1

Listing price <u>View report</u>



#### source: autotrader.co.uk

#### Entry 1

Date	2022-01-15
Pictures	13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2023-09-15
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	38
Total items failed	18

MOT #22	2022-09-16 14:50
MOT test number	635602509985
Result	✓ Passed
Next expiry date	2023-09-15

MOT #21	2021-07-12 15:51
MOT test number	123455640730
Result	✓ Passed

MOT #20	2021-07-12 09:45
MOT test number	491908213700
Result	<b>X</b> Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge outer edge bald (5.2.3 (e))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge inner edge bald (5.2.3 (e))

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #19	2020-07-15 08:48
MOT test number	472785674042
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #18

MOT test number

Result

Advice Steering column universal joint very rust,

Advice Rear suspension very rusty.

**MOT #17** 2019-07-23 11:03 **MOT** test number 533113258056 Result **X** Failed Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Fail Emissions not tested fuel leak. (8.2.1.2 (d)) Advice Steering column universal joint very rust, Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Nearside Rear Fuel pipe leaking Fuel pipes rusty. (6.1.3 (b) (i)) **Advice** Rear suspension very rusty. Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #16		2018-08-03 15:07
MOT test nui	mber	344367998953
Result		<b>✓</b> Passed
<b>Advice</b> St	teering system corroded.	
<b>Advice</b> N (5.3.4 (a) (i))	earside Front Upper Suspension arm pin or bush worn but not re	esulting in excessive movement
<b>Advice</b> A	ll fuel pipes corroded.	

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #15** 2018-07-30 09:14 **MOT** test number 745225705753 Result **X** Failed Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) **Advice** Steering system corroded. Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Nearside Rear Brake pipe at imminent risk of failure or fracture (1.1.11 (a)) Fail Fail Brake performance not tested Brake fluid leak N/S/rear. (1.2.1 (g)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice All fuel pipes corroded. **Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b)) Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Fail Nearside Rear Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii)) Fail Offside Rear Brake pipe at imminent risk of failure or fracture (1.1.11 (a))

MOT #14	2017-08-10 12:08
MOT test number	185752285481
Result	<b>✓</b> Passed
Advice Brake pipe slightly corroded both front to rear at rear (3.6.B.2c)	

CarCheck.co.uk page 5/13



report date: 2024-03-28

**MOT #13** 2017-08-09 12:01

**MOT test number** 352842416782

Result X Failed

Fail Headlamp cleaning device inoperative both (1.7.2)

**Advice** Brake pipe slightly corroded both front to rear at rear (3.6.B.2c)

**Fail** Windscreen washer provides insufficient washer liquid all (8.2.3)

**Fail** Registration plate lamp not working both (1.1.C.1d)

**Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

MOT #12 2015-03-25 14:45

MOT test number 209494985017

Result \rightarrow Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2014-03-11 11:55

MOT test number 647550374081

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #10** 2013-03-19 10:48

MOT test number 666318273035

**Result** ✓ Passed

Advice Front Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #9 2013-03-13 15:34

**MOT test number** 897642273020

**Result** X Failed

Advice Front Headlamp has a product on the light source but not seriously reducing light output (1.7.5a)

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #8 2012-03-28 13:08

**MOT test number** 476828982017

**Result** ✓ Passed

MOT #7 2011-03-22 11:33

**MOT test number** 269841081021

Result \rightarrow Passed

**MOT #6** 2010-03-30 16:25

**MOT test number** 493509080077

Result \rightarrow Passed

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** Engine warning light on

**Notice** Nearside front wheel binding slightly

MOT #5 2009-03-30 14:51

**MOT test number** 712009289039

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/13



report date: 2024-03-28

MOT #4 2008-02-27 10:25

MOT test number 223028358043

Result ✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear brake disc slightly pitted (3.5.1h)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Rear tyres at 3mm

**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)

MOT #3 2007-04-04 17:23

MOT test number 194444397476

**Result** ✓ Passed

MOT #2 2007-04-04 11:20

MOT test number 854414597009

**Result** X Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Anti-roll bar linkage insecure (2.4.G.1)

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #1** 2006-09-05 12:34

**MOT test number** 241658746258

**Result** 
✓ Passed

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
*********	
***************************************	
********	
***************************************	
***********	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NAME OF THE PARTY OF THE PAR
Plate since	

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2000-03-21
Last registration	2022-09-16
Complete history	See info



Registration #1	2000-03-21	28 mi
Registration #2	2006-09-05	44.050 mi
Registration #3	2007-04-04	47.084 mi
Registration #4	2007-04-04	47.090 mi
Registration #5	2008-02-27	56.535 mi
Registration #6	2009-03-30	68.630 mi
Registration #7	2010-03-30	78.476 mi
Registration #8	2011-03-22	88.299 mi
Registration #9	2012-03-28	96.354 mi
Registration #10	2013-03-13	105.514 mi
Registration #11	2013-03-19	105.653 mi
Registration #12	2014-03-11	115.885 mi
Registration #13	2015-03-25	127.586 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		70.777 es
Registration #24		
Registration #24		11.777 es



report date: 2024-03-28

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1860 mm
Height	1285 mm
Length	4135 mm
Kerb weight	1271 kg

## Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	F20C21002819

CarCheck.co.uk page 13/13