



report date: 2024-03-29

General information

Make	MAZDA
Model	6 D SPORT
Colour	Blue
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	142 g/km
CO2 label	F





## MOT history

MOT expiry date	2025-04-25
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #14	2024-04-20 11:18
MOT test number	980488404029
Result	✓ Passed
Next expiry date	2025-04-25

MOT #13	2024-04-20 11:18
MOT test number	193693763391
Result	✗ Failed
<b>Pass with rectification</b> Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #12	2023-03-31 13:54
MOT test number	197596748811
Result	✓ Passed

MOT #11	2022-04-16 11:11
MOT test number	507420703361
Result	✓ Passed
<b>Minor</b> Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))	
<b>Advice</b> Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Advice</b> Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Advice</b> Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

**MOT #10** 2021-04-26 09:37**MOT test number** 464210588312**Result** ✓ Passed**MOT #9** 2021-04-26 09:37**MOT test number** 102621019554**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #8** 2019-05-17 08:43**MOT test number** 350629284779**Result** ✓ Passed**MOT #7** 2018-05-29 15:17**MOT test number** 289737144423**Result** ✓ Passed**MOT #6** 2017-05-10 15:34**MOT test number** 322609003955**Result** ✓ Passed**Advice** Nearside Rear tyre wearing on inner edge**Advice** Offside Front tyre has small cut in outer tread**Advice** Both front tyres wearing on edges**Advice** Offside Rear tyre slightly out of shape and wearing on inner edge

**MOT #5** 2017-05-10 09:08**MOT test number** 663036824875**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front tyre has small cut in outer tread**Advice** Both front tyres wearing on edges**Advice** Offside Rear tyre slightly out of shape and wearing on inner edge**Advice** Nearside Rear tyre wearing on inner edge**MOT #4** 2016-05-25 11:27**MOT test number** 292086699979**Result** ✓ Passed**Advice** Offside Rear tyre has nail in tread**MOT #3** 2015-06-15 09:32**MOT test number** 446526065103**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2014-06-18 17:21**MOT test number** 439949264132**Result** ✓ Passed**MOT #1** 2013-10-21 13:01**MOT test number** 515374193213**Result** ✓ Passed**Notice** Offside front tyre worn low on inner & outer edges



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
25 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	3
<b>MOT expiry date</b>	25 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>GV60YYS</b>
Plate since	2024-03-29
Current registration	<b>GV60YYS</b>
Plate since	2024-03-29

More info >





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-04
Last registration	2024-04-20
Complete history	<a href="#">See info</a>



Registration #1	2010-11-04	18 mi
Registration #2	2013-10-21	14.752 mi
Registration #3	2014-06-18	18.864 mi
Registration #4	2015-06-15	25.269 mi
Registration #5	2016-05-25	31.966 mi
Registration #6	2017-05-10	39.355 mi
Registration #7	2017-05-10	39.355 mi
Registration #8	2018-05-29	47.047 mi
Registration #9	2019-05-29	55.337 mi
Registration #10	2020-05-29	63.627 mi
Registration #11	2021-05-29	71.917 mi
Registration #12	2022-05-29	80.207 mi
Registration #13	2023-05-29	88.497 mi
Registration #14	2024-04-20	96.787 mi
Registration #15	2024-04-20	96.787 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10241636