



**BFIIJAU**

report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 90
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 2


Date	2022-03-20
Pictures	10
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

Date	2021-11-21
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2024-11-27
MOT pass rate	53 %
MOT passed	10
Failed MOT tests	9
Total advice items	17
Total items failed	26

MOT #19	2023-11-28 10:20
MOT test number	135621100027
Result	✓ Passed
Next expiry date	2024-11-27
Advice	Surface corrosion on suspension and braking

MOT #18	2022-11-25 08:48
MOT test number	471980442731
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-11-25 08:48
MOT test number	958283767995
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2021-11-02 14:45**MOT test number** 413207625413**Result** ✓ Passed**MOT #15** 2021-11-02 14:45**MOT test number** 757285064275**Result** ✗ Failed

**Pass with rectification** Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #14** 2020-10-26 16:24**MOT test number** 925961652038**Result** ✓ Passed**MOT #13** 2020-10-16 16:26**MOT test number** 898434296537**Result** ✗ Failed

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #12** 2019-10-29 11:04**MOT test number** 192641932795**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge needs replacing (5.2.3 (e))

**MOT #11** 2019-10-24 10:49**MOT test number** 910624413802**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge needs replacing (5.2.3 (e))**Fail** Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Central Stop lamp(s) all not working (4.3.1 (a) (iii))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #10** 2017-12-14 15:28**MOT test number** 977786841786**Result** ✓ Passed**Advice** Tank strap missing but tank supported**MOT #9** 2017-12-08 12:40**MOT test number** 530189355643**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Advice** Tank strap missing but tank supported**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**MOT #8** 2016-11-30 16:52**MOT test number** 220765016335**Result** ✓ Passed

**MOT #7** 2016-11-30 10:39**MOT test number** 145854566219**Result** ✗ Failed

- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2015-11-25 09:42**MOT test number** 573937755166**Result** ✓ Passed

- Advice** Nail in n/s front tyre
- Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)

**MOT #5** 2015-11-23 12:40**MOT test number** 692499836466**Result** ✗ Failed

- Advice** Nearside Front Macpherson strut has slight movement in the upper support bearing assembly (2.5.B.1b)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside front brake excessively fluctuating (3.7.B.3)
- Advice** Nail in n/s front tyre
- Fail** Centre Stop lamp not working (1.2.1b)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #4** 2015-02-27 13:38**MOT test number** 605608555057**Result** ✓ Passed

**MOT #3** 2015-02-27 12:48**MOT test number** 746388155023**Result** ✗ Failed**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #2** 2014-02-26 15:27**MOT test number** 877727054047**Result** ✓ Passed**Notice** Header tank empty and pipe split**MOT #1** 2014-02-26 11:29**MOT test number** 756847754090**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Header tank empty and pipe split



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
27 November 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		27 November 2024
Full MOT history		<a href="#">See MOT history</a>





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-03-18
Last registration	2023-11-28
Complete history	<a href="#">See info</a>



Registration #1	2011-03-18	16 mi
Registration #2	2014-02-26	52.373 mi
Registration #3	2014-02-26	52.374 mi
Registration #4	2015-02-27	107.878 mi
Registration #5	2015-11-23	76.489 mi
Registration #6	2015-11-25	76.490 mi
Registration #7	2016-11-30	88.830 mi
Registration #8	2016-11-30	88.830 mi
Registration #9	2017-12-08	101.436 mi
Registration #10	2017-12-14	101.436 mi
Registration #11	2019-10-24	200.656 mi
Registration #12	2019-10-24	200.656 mi
Registration #13	2019-10-24	200.656 mi
Registration #14	2019-10-24	200.656 mi
Registration #15	2019-10-24	200.656 mi
Registration #16	2019-10-24	200.656 mi
Registration #17	2019-10-24	200.656 mi
Registration #18	2019-10-24	200.656 mi
Registration #19	2019-10-24	200.656 mi
Registration #20	2019-10-24	200.656 mi
Registration #21	2019-10-24	200.656 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1942 mm
Length	4805 mm
Wheel base	3000 mm
Kerb weight	1661 kg
Max. allowed weight	2661 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBBY0052390