



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B200 CDI SE
Colour	Blue
Year of manufacture	2007
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	300 Nm at 3.000 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-20
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-21
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	18
Total items failed	16

MOT #24	2024-01-05 16:24
MOT test number	469073477588
Result	✓ Passed
Next expiry date	2025-01-21

MOT #23	2024-01-05 12:18
MOT test number	346014727303
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #22	2023-01-17 15:51
MOT test number	849283036858
Result	✓ Passed

MOT #21	2022-01-22 09:41
MOT test number	993125055746
Result	✓ Passed

**MOT #20** 2022-01-14 12:17**MOT test number** 562121644425**Result** ✗ Failed**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Fuel system component leaking filler neck (6.1.3 (b) (i))**Fail** Nearside Rear Seat belt buckle damaged (7.1.2 (d))**MOT #19** 2021-01-05 14:56**MOT test number** 367682877659**Result** ✓ Passed**MOT #18** 2021-01-05 12:09**MOT test number** 281549533750**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #17** 2020-01-02 11:39**MOT test number** 966971915984**Result** ✓ Passed**Advice** Plastic under trays covering front to rear metal brake pipes**MOT #16** 2018-12-27 09:48**MOT test number** 347455402099**Result** ✓ Passed

**MOT #15** 2018-12-14 10:56**MOT test number** 117862084034**Result** ✗ Failed**Fail** Nearside Rear Passenger's seat with a defective structure seatbelt buckle broken (6.2.6 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #14** 2018-03-02 09:37**MOT test number** 279147558714**Result** ✓ Passed**MOT #13** 2018-03-02 09:37**MOT test number** 585360187979**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #12** 2017-03-03 14:19**MOT test number** 433343062097**Result** ✓ Passed**MOT #11** 2016-03-03 16:09**MOT test number** 452397450337**Result** ✓ Passed**Advice** Plastic covers fitted**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2016-02-25 16:06

MOT test number

171326008897

Result**✗ Failed**

Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Plastic covers fitted

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front coil spring broken (2.4.C.1a)

MOT #9

2015-02-26 09:26

MOT test number

156697855068

Result**✓ Passed****MOT #8**

2014-02-21 15:24

MOT test number

328032354022

Result**✓ Passed**

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7

2014-02-21 10:28

MOT test number

496232854043

Result**✗ Failed**

Fail Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Advice Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #6** 2013-01-24 11:06**MOT test number** 658574423028**Result** ✓ Passed**MOT #5** 2012-02-10 10:54**MOT test number** 389041942075**Result** ✓ Passed**Notice** Both rear tyres wearing out of shape on inner edges.**Notice** Rear brake discs slightly scored.**MOT #4** 2012-02-10 10:28**MOT test number** 967001542011**Result** ✗ Failed**Notice** Both rear tyres wearing out of shape on inner edges.**Notice** Rear wiper blade split**Fail** Nearside Body has a sharp edge caused by damage (6.1.C.1)**Notice** Rear brake discs slightly scored.**MOT #3** 2011-02-02 15:44**MOT test number** 495123031051**Result** ✓ Passed**MOT #2** 2011-02-02 10:58**MOT test number** 478283831017**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #1	2010-01-22 09:28
MOT test number	520812420077
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-02-22
Last registration	2024-01-05
Complete history	See info



Registration #1	2007-02-22	11 mi
Registration #2	2010-01-22	14.294 mi
Registration #3	2011-02-02	19.206 mi
Registration #4	2011-02-02	19.206 mi
Registration #5	2012-02-10	24.539 mi
Registration #6	2012-02-10	24.539 mi
Registration #7	2013-01-24	27.946 mi
Registration #8	2014-02-21	31.545 mi
Registration #9	2014-02-21	31.545 mi
Registration #10	2015-02-26	34.242 mi
Registration #11	2016-02-25	36.011 mi
Registration #12	2016-03-03	36.039 mi
Registration #13	2017-03-03	37.496 mi
Registration #14	2018-03-03	38.953 mi
Registration #15	2019-03-03	40.410 mi
Registration #16	2020-03-03	41.867 mi
Registration #17	2021-03-03	43.324 mi
Registration #18	2022-03-03	44.781 mi
Registration #19	2023-03-03	46.238 mi
Registration #20	2024-01-05	47.695 mi
Registration #21	2024-01-05	47.695 mi
Registration #22	2024-01-05	47.695 mi
Registration #23	2024-01-05	47.695 mi
Registration #24	2024-01-05	47.695 mi
Registration #25	2024-01-05	47.695 mi
Registration #26	2024-01-05	47.695 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094130323012