





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE EXTREME DCI
Colour	Grey
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	200 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-08

Pictures 57

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #14 2022-06-06 08:38

MOT test number 983632753826

Result \rightarrow Passed

Next expiry date 2023-06-06

MOT #13 2021-06-07 09:11

MOT test number 585454975541

Result \rightarrow Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12 2021-06-04 17:19

MOT test number 341967757036

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Fail Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #11 2020-09-17 08:13

MOT test number 585073253978

Result
✓ Passed

MOT #10 2019-09-24 08:18

MOT test number 297592587060

Result

Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #8

MOT test number

584176360013

Result

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7

MOT test number

104122596736

Result

Advice

Offside + nearside rear tyre s slightly perished

MOT #6 2017-09-15 10:10 766222119451 **MOT** test number Result × Failed Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g) **Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g) Advice Offside Rear Brake pad(s) wearing thin (3.5.1g) **Advice** Offside + nearside rear tyre s slightly perished

CarCheck.co.uk page 4/12



MOT #5 2016-09-23 09:13

MOT test number 690427800356

Result ✓ Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-09-23 09:13

MOT test number 952456492097

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2015-09-17 10:27

MOT test number 369815860479

Result ✓ Passed

MOT #2 2014-09-19 10:19

MOT test number 338702764466

Result
✓ Passed

CarCheck.co.uk page 5/12



MOT #1 2013-09-25 12:07

MOT test number 637948263242

Result ✓ Passed

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

•		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-02
Last registration	2022-06-06
Complete history	See info



Registration #1	2010-09-02	10 mi
Registration #2	2013-09-25	42.034 mi
Registration #3	2014-09-19	45.944 mi
Registration #4	2015-09-17	51.825 mi
Registration #5	2016-09-23	56.891 mi
Registration #6	2016-09-23	56.891 mi
Registration #7	2017-09-15	61.614 mi
Registration #8	2017-09-15	61.614 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.77 66
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.777 mg

More info >

page 11/12 CarCheck.co.uk



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2037 mm
Height	1471 mm
Length	4295 mm
Wheel base	2641 mm
Max. allowed weight	1743 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

D051706