





report date: 2024-03-28

General information

Make	KIA
Model	CEED CRDI 2 SW
Colour	Grey
Year of manufacture	2011
Top speed	116 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	255 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-06-11	
Pictures	1	
Listing price	View report	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-27
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #12		2023-06-23 09:28
MOT test	number	939859363735
Result		✓ Passed
Next expi	ry date	2024-06-27
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11		2023-06-23 09:28
MOT test	number	917236088561
Result		X Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt		
Pass wit	h rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10		2022-06-27 13:49
MOT test	number	367690604238
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge inside edges (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriora	ted (5.3.4 (b) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))		
MOT #9		2021-06-28 14:59
MOT test number		219384177855
Result		✓ Passed
MOT #8		2020-07-14 08:45
MOT test number		891790872896
Result		✓ Passed
MOT #7		2019-07-10 09:09
MOT test number		124361009152
Result		✓ Passed
MOT #6		2018-07-09 09:22
MOT test number		495657025135
Result		✓ Passed
MOT #5		2018-07-09 09:22
MOT test number		883302643421
Result		★ Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4		2017-07-24 15:58
MOT test	number	867222283192
Result		✓ Passed
Advice	Front both front tyres wearing inner edge	
Advice	Offside Rear tyre wearing inner edge	

MOT #3	2016-07-26 11:53
MOT test number	235759324637
Result	✓ Passed
MOT #2	2015-07-16 14:01
MOT test number	147057795164
Result	✓ Passed
Notice Vehicle's internal headlight adjuster altered to recheck lights	
Notice Under-trays fitted obscuring some underside components	

MOT #1	2014-08-04 15:46
MOT test number	838146614227
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here .	

	More info >
	More into >
Plate changes	
See in this check if this KIA had different number plates.	
See in this eneck is this fairthad different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK
Plate since	m-n-n
	Mana infa
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-30
Last registration	2023-06-23
Complete history	See info



Registration #1	2011-09-30	26 mi
Registration #2	2014-08-04	8.155 mi
Registration #3	2015-07-16	19.650 mi
Registration #4	2016-07-26	32.533 mi
Registration #5	2017-07-24	45.080 mi
Registration #6	2018-07-09	54.416 mi
Registration #7	2018-07-09	54.416 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1525 mm
Length	4490 mm
Wheel base	2650 mm
Kerb weight	1502 kg
Max. allowed weight	1920 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 12/12