



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ CRTD GSI
Colour	Grey
Year of manufacture	2007
Top speed	107 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	191 Nm at 2.500 rpm
Engine capacity	1.493 cc
Cylinders	3
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	118 g/km
CO2 label	C





MOT history

MOT expiry date	2024-07-05
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	33
Total items failed	4

MOT #17	2023-06-23 10:41
---------	------------------

MOT test number	318769319047
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-05
------------------	------------

- Minor

Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))
- Advice

Rear rear axel corroded
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Front subframe corroded front
- Advice

Rear Coil spring corroded both sides (5.3.1 (b) (i))



MOT #16

2022-07-05 07:35

MOT test number

563967649234

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

2022-07-01 10:39

MOT test number

748477755859

Result

✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced Sill (7.1.1 (a) (i))
- Advice** Nearside Front Inner Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #14**

2021-06-14 07:58

MOT test number

235657677967

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive Outer sill area (7.1.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2020-06-12 10:40

MOT test number

610808257313

Result

✓ Passed

MOT #12

2019-06-28 12:42

MOT test number

827164842316

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

2018-07-06 11:33

MOT test number

622396478636

Result

✓ Passed

- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))
- Advice** Offside Rear Nail in tyre

MOT #10

2017-07-01 09:32

MOT test number

451144570913

Result

✓ Passed

**MOT #9** 2017-07-01 08:44**MOT test number** 868098934094**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2016-07-01 09:35**MOT test number** 869759172097**Result** ✓ Passed**Advice** Handbrake Lever Has Slight Travel**Advice** O/S/R Tyre Cracking Lightly On Outer Sidewall**Advice** Offside Front Tyre worn close to the legal limit Inside Edge (4.1.E.1)**MOT #7** 2014-12-01 11:50**MOT test number** 466005934333**Result** ✓ Passed**MOT #6** 2013-11-07 15:05**MOT test number** 625761313312**Result** ✓ Passed**MOT #5** 2012-08-13 15:13**MOT test number** 259426422208**Result** ✓ Passed**MOT #4** 2011-07-18 12:39**MOT test number** 825069991173**Result** ✓ Passed



MOT #3	2011-07-12 13:17
MOT test number	477893991184
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Headlamp does not operate immediately when selected on dipped beam (1.7.4a)

MOT #2	2010-07-08 10:42
MOT test number	123089780125
Result	✓ Passed

MOT #1	2010-07-08 10:42
MOT test number	812019280108
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	KT07WJM
Plate since	2024-03-29
Current registration	KT07WJM
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-07-11
Last registration	2023-06-23
Complete history	See info



Registration #1	2007-07-11	18 mi
Registration #2	2010-07-08	31.840 mi
Registration #3	2011-07-12	36.556 mi
Registration #4	2011-07-18	36.556 mi
Registration #5	2012-08-13	40.979 mi
Registration #6	2013-11-07	46.432 mi
Registration #7	2014-12-01	51.446 mi
Registration #8	2016-07-01	58.739 mi
Registration #9	2017-07-01	65.068 mi
Registration #10	2019-06-20	75.377 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1500 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1204 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4FA7U300118