



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 SE LUX
Colour	Black
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-03
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-02
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #10	2023-07-27 10:42
MOT test number	377546328962
Result	✓ Passed
Next expiry date	2024-08-02

MOT #9	2022-07-29 12:35
MOT test number	967975210532
Result	✓ Passed
Advice	Front wishbone bushes worn and splitting
Advice	Engine covers fitted

MOT #8	2021-08-03 12:43
MOT test number	376222219806
Result	✓ Passed

MOT #7	2020-09-23 07:56
MOT test number	406808695556
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin front pads low (1.1.13 (a) (ii))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge inner tread very low (5.2.3 (e))
Advice	Front Tyre worn close to legal limit/worn on edge Both front tyres very low (5.2.3 (e))

**MOT #6** 2019-09-23 11:12**MOT test number** 541392279886**Result** ✓ Passed**MOT #5** 2018-09-25 10:14**MOT test number** 983528017540**Result** ✓ Passed**MOT #4** 2017-09-28 13:59**MOT test number** 370415398228**Result** ✓ Passed**MOT #3** 2016-09-22 11:55**MOT test number** 689664151200**Result** ✓ Passed**Advice** Nearside Front driving lamp not working**MOT #2** 2016-09-22 11:55**MOT test number** 100347802850**Result** ✗ Failed**Advice** Nearside Front driving lamp not working**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**MOT #1** 2015-09-24 13:25**MOT test number** 141018199338**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-24
Last registration	2023-07-27
Complete history	See info



Registration #1	2012-09-24	7 mi
Registration #2	2015-09-24	9.758 mi
Registration #3	2016-09-22	14.194 mi
Registration #4	2016-09-22	14.194 mi
Registration #5	2017-09-28	17.659 mi
Registration #6	2018-09-25	18.230 mi
Registration #7	2019-09-22	20.277 mi
Registration #8	2019-09-22	20.277 mi
Registration #9	2019-09-22	20.277 mi
Registration #10	2019-09-22	20.277 mi
Registration #11	2019-09-22	20.277 mi
Registration #12	2019-09-22	20.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4615 mm
Wheel base	2640 mm
Kerb weight	1773 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number

995146