



T5PVW

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CARAVELLE S TDI
Colour	Blue
Year of manufacture	2003
Top speed	104 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	34.5 mpg
CO2 emission	221 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-09-03
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-29
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	31
Total items failed	13

MOT #21	2023-06-30 14:10
MOT test number	905952977207
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #20	2022-05-10 09:26
MOT test number	850761756757
Result	✓ Passed

MOT #19	2021-05-13 11:42
MOT test number	686619036775
Result	✓ Passed

MOT #18	2019-12-02 13:09
MOT test number	740246390801
Result	✓ Passed

MOT #17	2018-07-27 13:46
MOT test number	493271772929
Result	✓ Passed

**MOT #16** 2017-07-26 12:26**MOT test number** 302680380448**Result** ✓ Passed**MOT #15** 2016-07-30 09:56**MOT test number** 496151870267**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Plastic under trays fitted**MOT #14** 2015-07-10 11:11**MOT test number** 688401895179**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Rear Lower Coil spring mounting damaged but not seriously weakened (2.4.C.3c)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #13** 2014-07-02 16:58**MOT test number** 195723584152**Result** ✓ Passed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Both headlamp reflectors burnt badly

**MOT #12**

2014-07-02 10:34

MOT test number

389513084184

Result**✗ Failed****Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** Both headlamp reflectors burnt badly**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11**

2013-06-28 17:09

MOT test number

416999673138

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Coolant leak**Notice** Offside rear roadspring rubber mounting distorted

**MOT #10** 2013-06-28 12:28**MOT test number** 229099373178**Result** ✗ Failed

- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Notice** Coolant leak
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Offside rear roadspring rubber mounting distorted
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #9 2012-07-13 17:12**MOT test number** 275755592427**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #8 2012-07-11 17:33**MOT test number** 148153192189**Result** ✗ Failed

- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Headlamp aim too low (1.8)
- Advice** Offside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)

**MOT #7** 2011-07-15 14:29**MOT test number** 266136491404**Result** ✓ Passed**MOT #6** 2010-06-29 14:43**MOT test number** 890810280152**Result** ✓ Passed**MOT #5** 2010-06-29 14:43**MOT test number** 613830280111**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp not working (1.2.1b)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Pass with rectification** Front registration plate insecure (6.3.1b)

MOT #4 2009-07-01 14:59**MOT test number** 772712389181**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** O/s mirror glass cracked but still provides good view to the rear

MOT #3 2008-07-01 10:20**MOT test number** 294633788466**Result** ✓ Passed

- Notice** Rear suspension coil springs to trailing arms mountings slight deterioration

MOT #2 2007-11-07 15:01**MOT test number** 461991617398**Result** ✓ Passed



MOT #1	2006-11-10 11:28
MOT test number	964364116350
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 T5PVW
Plate since	2019-09-29
Current registration	 T5PVW
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-11-12
Last registration	2023-06-30
Complete history	See info



Registration #1	2003-11-12	26 mi
Registration #2	2006-11-10	45.083 mi
Registration #3	2007-11-07	55.431 mi
Registration #4	2008-07-01	59.564 mi
Registration #5	2009-07-01	83.951 mi
Registration #6	2010-06-29	94.972 mi
Registration #7	2011-07-15	103.430 mi
Registration #8	2012-07-11	109.753 mi
Registration #9	2012-07-13	109.753 mi
Registration #10	2013-06-28	118.556 mi
Registration #11	2013-06-28	118.556 mi
Registration #12	2013-06-28	118.556 mi
Registration #13	2013-06-28	118.556 mi
Registration #14	2013-06-28	118.556 mi
Registration #15	2013-06-28	118.556 mi
Registration #16	2013-06-28	118.556 mi
Registration #17	2013-06-28	118.556 mi
Registration #18	2013-06-28	118.556 mi
Registration #19	2013-06-28	118.556 mi
Registration #20	2013-06-28	118.556 mi
Registration #21	2013-06-28	118.556 mi
Registration #22	2013-06-28	118.556 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1949 mm
Length	4890 mm

Additional information

Number of axles	2
Engine number	AXD 008314